

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20004448/UGA3Q2

**Date:** 13/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> GBC1100Z	<b>Insured Vehicle No :</b>	SH7181Y
Date of Loss: 20/03/2020	Nature of Claim: TP	Claim No: MCT20030353

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC1100Z		
Make & Model:	KIA K2900, 2.9 D (M)	Engine No:	J3B114532
Reg. Date:	20/05/2011 (Man. Year: 2011)	Chassis No:	KNCSJX74LB7573891
Colour:	Silver	Odometer:	262482 km
Engine Capacity:	2902 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Hankook 6 mm	Rear Left Side:	Thunderer 6/6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Thunderer 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,046.80	3,275.80	4,771.00	59.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,240.00	830.00	40.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,116.80</b>	<b>4,515.80</b>	<b>5,601.00</b>	<b>55.36</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,116.80</b>	<b>3,600.00</b>	<b>6,516.80</b>	<b>64.42</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>3,907.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>3,900.00</b>		

### INSPECTION

Date of Assignment:	24/03/2020	
Date Inspected:	24/03/2020 Inspected At:	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Jul 2020)	
<b>Parts:</b>	N/A	KIA K2900 2.9 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC1100Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	2,152.00 FL	*1,525.00 FL
2	2		*REAR TAILGATE SIDE LOCK	Not Necessary	150.00 FL	*- FL
3	1		*REAR TAILGATE LOWER MEMBER	Repair	1,120.00 FL	*- FL
4	2		*REAR TAILGATE HINGES	Not Necessary	96.00 FL	*- FL
5	1		*REAR TAILGATE CEBTRE HINGE	Not Necessary	48.00 FL	*- FL
6	2		*RHS & LHS TAILLAMP	Cracked	1,504.00 FL	*450.00 FL
7	1		*RHS & LHS TAILLAMP PANEL (HOUSING)	N/S Bent / O/S Repair	500.00 FL	*165.00 FL
8	1		*RHS & LHS TAILLAMP PANEL RUBBER STOPPER	N/S Cut	168.00 FL	*42.00 FL
9	1		*REAR EXHAUST PIPE	Repair	650.00 FL	*- FL
10	2		*REAR EXHAUST PIPE MOUNTINGS	Not Necessary	84.00 FL	*- FL
11	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
12	1		*REAR STEP FRAME (BAR)	Bent	450.00 FS	*450.00 FS
13	1		*REAR STEP FRAME (BAR) SUPPORT BRACKET		300.00 FS	*- FS
14	1		*SPARE TYRE (155R12C)	Not Necessary	180.00 FS	*- FS
15	1		*SPARE TYRE (195R15C)	Not Necessary	250.00 FS	*- FS
16	1		*SPARE TYRE SUPPORT BRACKET	Bent	150.00 FS	*150.00 FS
17	1		*REAR TAILGATE COMPANY STICKER (W/LABOUR)	Necessary	360.00 FS	*360.00 FS
18	1		*REAR TAILGATE 6 PAX STICKER	Necessary	20.00 FS	*10.00 FS
19	1		*REAR TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
20	1		*REAR LICENCE PLATE W/HOLDER	Bent	75.00 FS	*40.00 FS
21	1		*REAR LICENCE PLATE LAMP BRACKET	Bent	92.00 FS	*92.00 FS
22	5		*REAR TAILGATE CANVAS COVER HOOKS	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,694.00</b>	<b>3,494.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	647.20	218.20
<b>Total Parts (\$\$)</b>	<b>8,046.80</b>	<b>3,275.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE THE AFFECTED PARTS TO COMMENCE REPAIRS, REPLACE DAMAGED PARTS	New	1,000.00	580.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	600.00	520.00
3	TO REMOVE AND REPLACE REVERSE SENSORS & CHECK FOR PROPER FUNCTION	New	120.00	50.00
4	TO REPLACE REAR EXHAUST PIPE AND CHECK FOR SYSTEM FUNCTION	New	200.00	60.00
5	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,070.00</b>	<b>1,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >