

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17022730/SES3Q2-1

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100095666-09

Claimant
Vehicle No : SHB5667M **Insured Vehicle No :** GU5865U

Date of Loss: 24/11/2017 Nature of Claim: TP Claim No: 8910432272SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5667M		
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Engine No:	Z20S1464528K
Reg. Date:	11/05/2012 (Man. Year: 2012)	Chassis No:	KL1LA69RJBB126968
Colour:	Maroon	Odometer:	800770 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R15	Rear Tyre Size:	205/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,041.40	1,589.30	1,452.10	47.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,092.00	1,110.00	982.00	46.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,133.40	2,699.30	2,434.10	47.42
Approved Total (Overridden) (\$\$)		2,400.00		
Nett Amount (\$\$)	5,133.40	2,400.00	2,733.40	53.25
+ Loss of Use (5.5 x S\$106.00/day) (\$\$)		583.00		
+ Car Rental (5.5 x S\$100.05/day) (\$\$)		550.28		
+ Doc/Search Fee (\$\$)		5.00		
Nett Liability (\$\$)		3,538.28		
Global Sum Settlement (\$\$)		3,500.00		

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER LH REAR (DISC 10%)	Dented	1,191.00 F	*1,071.90 F
2	1		*MOLDING WINDSCREEN REAR (DISC 10%)	Necessary	45.00 F	*40.50 F
3	1		*LAMP RR COMBINATION LH (DISC 10%)	Scratched	415.00 F	*373.50 F
4	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
5	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
6	2		*SEALANT W/SCREEN (SN)	Necessary	74.00 F	*74.00 F
7	1		*BUMPER RR	Repair	1,238.00 F	*- F
8	1		*BRACKET RR BUMPER SIDE LH	Not Necessary	49.00 F	*- F

F=Franchise part.

Total Parts (S\$) **3,041.40** **1,589.30**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	676.00	400.00
2	SPRAY PAINT	New	756.00	400.00
3	TOWING CHARGE	New	80.00	80.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
6	TO REMOVE/REFIT SEAT	New	120.00	60.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	110.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$)			2,092.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >