

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004451/KEA3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100416468

Claimant
Vehicle No : SLH463M **Insured Vehicle No :** SKT4792K

Date of Loss: 24/03/2020 Nature of Claim: TP Claim No: 5687821666SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH463M	Engine No:	2ZRR961504
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU303537264
Reg. Date:	21/10/2016 (Man. Year: 2016)	Odometer:	181043 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	512.61	0.00	512.61	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	637.70	329.70	308.00	48.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,150.31	329.70	820.61	71.34
+ GST 7.00/7.00% (\$\$)	80.52	23.08	57.44	71.34
Nett Amount (\$\$)	1,230.83	352.78	878.05	71.34
+ Car Rental (2.0 x S\$69.94/day) (\$\$)		139.88		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		500.11		

INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 26/03/2020 Inspected At: Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	149.70 FL	* - FL
2	1		*REAR COVER BUMPER	Serviceable	582.60 FL	* - FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	732.30	0.00
- List Item Discount on L Items 30.00/30.00% (\$)	219.69	0.00
Total Parts (\$)	512.61	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	67.0 WU X 50.00 SGD/H	New	335.00	75.00
2	LABOUR COST 49.0 WU X 50.00 SGD/H	New	245.00	200.00
3	MATERIAL COST	New	57.70	54.70
Gross Labour Cost (\$\$)			637.70	329.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >