

AUTOWORX HOUSE

C/O176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 6452 8211 FAX: 6451 7423

ESTIMATE

NOT Authorized
L1 Smp & 620dp Max
Recovery After Paint

E KAR WEI
 46 Lentor Plain
 Singapore 786548

Date : 29/5/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA AXIO / SJC 2052 C		
	front bonnet	<i>Bl</i> 675.90 ✓
	front bonnet hinge <i>e 113.20</i>	<i>Di/In</i> 348.40 ✓
	front bonnet stay rod @ 174.20	<i>R</i> 87.10 X
	front bonnet stay rod grommet	<i>Tn</i> 7.60 ✓
	front bonnet lock	<i>R</i> 176.40 ✓
	front bonnet lock cable	<i>Jm</i> 156.70 ✓
	front bonnet heat shield	<i>NJP</i> 195.50 X
	front bonnet rubber seal	<i>Tn</i> 95.30 ✓
	front head lamp assy @ 657.30	<i>Bn</i> 1,314.60 ✓
	front head lamp panel @ 216.3	<i>R</i> 432.60 ✓
	front radiator top panel	<i>R</i> 265.70 ✓
	front radiator centre brace panel	<i>R</i> 196.70 ✓
	front radiator lower panel	<i>R</i> 233.40 X
	front radiator side panel @ 267.80	<i>NJP</i> 535.60 X
	radiator	<i>Bl</i> 1,079.50 ✓
	radiator top bracket	<i>Di</i> 97.40 ✓
	radiator fan cowling	<i>CM</i> 216.40 ✓
	radiator fan motor	<i>Tn</i> 364.50 ✓
	radiator fan blade	<i>CM</i> 195.40 ✓
	radiator fan relay / resistor	<i>Jm</i> 378.40 X
	radiator top hose	<i>Jm</i> 167.50 X
	engine air intake duct	<i>Dd</i> 176.70 ✓
	engine air intake manifold	<i>Rd</i> 577.80 ✓
	engine air filter box	<i>CM</i> 340.50 ✓
	horn @ 176.40	<i>Dd</i> 352.80 ✓
	front bumper <i>478.80</i>	<i>Tn</i> 678.10 ✓
	front bumper fog lamp garnish @ 134.30	<i>Di</i> 268.60 ✓
	front bumper top grille	<i>NJP</i> <i>mi</i> 386.50 X
	front bumper fog lamp <i>e 347.60</i>	<i>m/cm</i> 878.20 ✓
	front bumper lower dust cover	<i>CM</i> 314.50 ✓
	front bumper reinforcement	<i>R</i> 331.40 ✓
	front bumper impact sponge	<i>mi</i> 198.90 ✓
	front bumper side retainer @ 74.50	<i>CM</i> 149.00 ✓
	front bumper clip @ 3.10	<i>mi</i> 31.00 ✓
	air con condenser	<i>Bl/In</i> 1,465.20 ✓
	Sub-total	13,369.80

Balance brought forward.		13,369.80
air con liquid pipe		Sm 278.70 X
air con high pressure hose		Sm 325.30 X
front fender	@ 578.20	Bu 1,156.40 ✓
front fender dust cover C174-10	@ 197.60	CM 395.20 ✓
front fender dust cover clip	@ 3.10	M 74.40 ✓
front grille		CM mit 577.40 ✓
front griller emblem 381.40		M 94.30 ✓
front grill clip	@ 3.10	M 24.80 ✓
fuse / relay junction box		Sm 371.40 X
front windscreen glass 1346.30		CM 1,655.10 ✓
front windscreen glass moulding		M 157.30 ✓
sub frame cross-member		Bu 431.30 ✓
front engine mount		CM 197.10 ✓
front engine mount bracket		Dis 87.50 ✓
air temperature sensor		Sm 215.90 X
	sub-total	19,411.90
	less 25%	4,852.98
	sub-total	14,558.93
number plate	s.nett	mit 45m { 35.00
number plate casing	s.nett	{ 35.00
radiator coolant	s.nett	M 80.60 25m
battery	s.nett	nd 195.00 50m
front windscreen glass inner seal	s.nett	30m 45.00
windscreen glass sealant	s.nett	40m 60.00
ERP IU bracket	s.nett	M 20.00 ✓
To remove & replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1100/ 2,000.00
To apply putty & spray painting on affected areas.		1200/ 1,400.00
To check wiring system.		20/ 50.00
To apply rust proofing on affected areas..		100.00 ✓
To apply waterproof sealant on affected areas.		60/ 80.00
To remove front windscreen glass to enable repair.		120/ 140.00
To remove & install front undercarriage parts to enable repair.		M 80.00 X
To repalce air con components and top up gas.		100/ 140.00
To bench mount & align chassis frame.		250/ 480.00
	sub-total	19,499.53

Balance brought forward.	19,499.53	
Towing charges.	50.00	✓
To remove & install engine components to enable repair.	<i>na</i> 120.00	X
Total	19,669.53	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: