

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004465/R1TF3E2

Date: 07/07/2021

REFERENCE

Insured/Claimant: STEPHEN SUTOPO Policy No: 1900085507
Date of Loss: 16/03/2020 Nature of Claim: OD Claim No: 3640018959SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS8231D**
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CHZC27815
Reg. Date: 09/04/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V4K1025575
Colour: White Odometer: 16026 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$97,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	115,225.60	78,149.64	37,075.96	32.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	40,764.00	28,604.00	12,160.00	29.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	155,989.60	106,753.64	49,235.96	31.56
Approved Total (Overridden) (S\$)		90,000.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	155,689.60	89,700.00	65,989.60	42.39
+ GST 7.00/7.00% (S\$)	10,898.27	6,279.00	4,619.27	42.39
Nett Amount (S\$)	166,587.87	95,979.00	70,608.87	42.39

INSPECTION

Date of Assignment: 25/03/2020

Date Inspected: 24/03/2020 Inspected At:

24 BENOI SECTOR

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 28.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,894.00 FS	*1,515.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	176.00 FS	*140.80 FS
3	1		*FRONT BUMPER GUIDE SECTION - LH / RH	N/S Not Necessary O/S Cracked	72.00 FS	*28.64 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	151.00 FS	*120.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	505.00 FS	*404.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	N/S Serviceable / O/S Missing	560.00 FS	*223.60 FS
7	2		*FRONT BUMPER COVER TRIM - LH / RH	Serviceable	306.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ADAPTER - LH / RH	N/S Serviceable /O/S Necessary	72.00 FS	*28.16 FS
9	1		*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,070.40 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	180.00 FS	*143.60 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Serviceable / O/S Missing	354.00 FS	*141.20 FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT	Bent	681.00 FS	*544.80 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	178.00 FS	*142.40 FS
14	1		*FOAM FILLER PIECE COVER	Cut	115.00 FS	*91.60 FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
16	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
17	1		*SIGNAL HORN - LH HIGH TONE	Serviceable	188.00 FS	*- FS
18	1		*SIGNAL HORN RH LOW TONE	Scratched	188.00 FS	*150.00 FS
19	2		*FRONT FENDER - LH / RH	Bent	1,604.00 FS	*1,282.40 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	68.00 FS	*55.60 FS
21	1		*FRONT FENDER BRACKET - RH	Bent	26.00 FS	*20.56 FS
22	1		*FRONT FENDER BRACKET - RH	Bent	36.00 FS	*28.80 FS
23	1		*FRONT FENDER BRACE	Bent	90.00 FS	*71.92 FS
24	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	31.00 FS	*24.56 FS
25	1		*FRONT FENDER INSULATION - RH	Necessary	40.00 FS	*31.76 FS
26	1		*WHEEL HOUSING LINER SEAL - RH	Necessary	32.00 FS	*25.44 FS
27	1		*WHEEL HOUSING LINER LH / RH	N/S Serviceable / O/S Deformed	318.00 FS	*254.40 FS
28	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	84.00 FS	*67.20 FS
29	1		*BONNET	Bent	2,988.00 FS	*2,390.40 FS
30	1		*BONNET ATTACHMENT PARTS	Necessary	155.00 FS	*123.20 FS
31	2		*BONNET LID HINGE - LH / RH	Bent	116.00 FS	*91.84 FS
32	1		*BONNET GAS FILLED STRUT	Serviceable	112.00 FS	*- FS
33	1		*BONNET CATCH HOOK	Bent	84.00 FS	*67.12 FS
34	1		*BONNET STRIKER - LH / RH	Serviceable	208.00 FS	*- FS
35	1		*BONNET EDGE PROTECTION	Necessary	26.00 FS	*20.80 FS
36	1		*BONNET COVER - RH	Deformed	39.00 FS	*30.48 FS
37	1		*WATER BOX SEAL	Not Necessary	56.00 FS	*- FS
38	2		*BONNET LID LOCK	Cracked	403.00 FS	*322.40 FS
39	1		*FLAT CONNECTOR HOUSING	Serviceable	13.00 FS	*- FS
40	1		*BONNET BOWDEN CABLE - CENTRE	Serviceable	54.00 FS	*- FS
41	1		*BONNET LID LOCK CABLE	Serviceable	69.00 FS	*- FS
42	1		*RELEASE HANDLE BRACKET	Serviceable	36.00 FS	*- FS
43	1		*ACTUATING LEVER	Serviceable	47.00 FS	*- FS
44	2		*WATER BOX SEAL - LH / RH	Not Necessary	26.00 FS	*- FS
45	1		*BONNET SOUND ABSORBER	Serviceable	207.00 FS	*- FS
46	1		*PLENUM CHAMBER COVER	Cut	169.00 FS	*135.20 FS
47	1		*SIDE MEMBER - RH UPPER	Bent	384.00 FS	*307.20 FS
48	2		*LED HEADLIGHT - LH / RH	Broken	10,386.00 FS	*8,308.80 FS
49	1		*MAIN LIGHTS POWER MODULE	Cracked	714.00 FS	*571.20 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Working	524.00 FS	*419.20 FS
51	1		*LED WITH HEAT SINK - RH	Bent	689.00 FS	*550.80 FS
52	1		*HEADLIGHT HOSE - RH	Serviceable	38.00 FS	*- FS
53	1		*LIFT CYLINDER - LH / RH	N/S Serviceable/O/S Broken	268.00 FS	*107.20 FS
54	1		*LIFT CYLINDER HOSE	Serviceable	64.00 FS	*- FS
55	1		*HEADLIGHT WASHER PUMP	Serviceable	149.00 FS	*- FS
56	1		*WINDSCREEN WASHER SYSTEM PUMP	Serviceable	120.00 FS	*- FS
57	1		*WASH WATER RESERVOIR	Serviceable	190.00 FS	*- FS
58	1		*LOCK CARRIER	Cracked	685.00 FS	*547.60 FS
59	1		*AIRCON CONDENSER	Bent	519.00 FS	*415.20 FS
60	1		*REFRIGERANT LINE	Cut	613.00 FS	*490.00 FS
61	1		*REFRIGERANT LINE	Cut	471.00 FS	*376.40 FS
62	1		*REFRIGERANT LINE BRACKET	Bent	25.00 FS	*20.00 FS
63	1		*REFRIGERANT LINE DUAL CLIP	Necessary	29.00 FS	*22.48 FS
64	1		*RADIATOR	Bent	932.00 FS	*745.20 FS
65	1		*ADDITIONAL RADIATOR	Bent	851.00 FS	*680.40 FS
66	2		*RADIATOR BRACKET	Necessary	78.00 FS	*62.24 FS
67	2		*RADIATOR BUSH - LOWER	Necessary	19.00 FS	*14.56 FS
68	1		*READY MIX COOLANT	Necessary	169.00 FS	*134.72 FS
69	1		*RADIATOR FAN	Serviceable	1,070.00 FS	*- FS
70	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	46.00 FS	*36.32 FS
71	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Serviceable	12.00 FS	*- FS
72	1		*EXTERNAL TEMPERATURE SENSOR	Not Working	55.00 FS	*43.84 FS
73	1		*TEMPERATURE SENSOR BRACKET	Necessary	18.00 FS	*13.76 FS
74	1		*AIR INTAKE AIR DUCT COVER	Serviceable	28.00 FS	*- FS
75	1		*AIR INTAKE AIR GUIDE	Serviceable	54.00 FS	*- FS
76	1		*AIR INTAKE AIR GUIDE	Serviceable	63.00 FS	*- FS
77	1		*AIR INTAKE SEAL	Not Necessary	13.00 FS	*- FS
78	1		*AIR INTAKE AIR FILTER	Serviceable	256.00 FS	*- FS
79	1		*AIR INTAKE AIR GUIDE	Serviceable	19.00 FS	*- FS
80	1		*AIR INTAKE WATER DRAINAGE HOSE	Serviceable	32.00 FS	*- FS
81	1		*AIR INTAKE MANIFOLD	Serviceable	131.00 FS	*- FS
82	1		*EXHAUST MANIFOLD	Serviceable	5,049.00 FS	*- FS
83	2		*OIL RETURN TUBE O-RING	Not Necessary	46.00 FS	*- FS
84	2		*INTAKE PIPE GASKET	Not Necessary	27.00 FS	*- FS
85	1		*CONVERTER AND PIPE GASKET	Not Necessary	19.00 FS	*- FS
86	1		*CONVERTER AND PIPE CLAMP	Not Necessary	48.00 FS	*- FS
87	1		*COOLANT HOSE	Serviceable	232.00 FS	*- FS
88	1		*COOLANT HOSE	Serviceable	115.00 FS	*- FS
89	1		*AIRCON COMPRESSOR	Not Necessary	2,123.00 FS	*- FS
90	1		*CHARGE AIR COOLER	Serviceable	686.00 FS	*- FS
91	1		*CHARGE AIR COOLER SEAL	Not Necessary	13.00 FS	*- FS
92	1		*CHARGE AIR COOLER SEAL	Not Necessary	13.00 FS	*- FS
93	1		*INTAKE MANIFOLD	Serviceable	600.00 FS	*- FS
94	1		*INTAKE MANIFOLD SEAL	Not Necessary	13.00 FS	*- FS
95	1		*SIDE PANEL - RH	Bent	2,063.00 FS	*1,650.40 FS
96	1		*WINDSCREEN	Cracked	1,020.00 FS	*816.00 FS
97	1		*RAIN SENSOR GEL FOIL	Necessary	130.00 FS	*104.00 FS
98	1		*INTERIOR MIRROR SPRING CLIP	Necessary	20.00 FS	*15.92 FS
99	1		*WATER DEFLECTOR STRIP - RH	Missing	87.00 FS	*69.44 FS
100	1		*FRONT DOOR - RH	Bent	2,375.00 FS	*1,900.00 FS
101	1		*FRONT OUTER DOOR SEAL - RH	Necessary	151.00 FS	*120.80 FS
102	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
103	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
104	1		*FRONT DOOR ATTACHMENT PARTS	Necessary	227.00 FS	*178.32 FS
105	1		*FRONT DOOR CATCH	Serviceable	99.00 FS	*- FS
106	1		*DOOR HINGE HALF - UPPER PART - RH UPPER	Serviceable	75.00 FS	*- FS
107	1		*DOOR HINGE HALF - UPPER PART - RH LOWER	Serviceable	45.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*DOOR HINGE HALF - LOWER PART - RH UPPER	Serviceable	45.00 FS	*- FS
109	1		*DOOR HINGE HALF - LOWER PART - RH LOWER	Serviceable	45.00 FS	*- FS
110	1		*FRONT WINDOW SLOT SEAL - RH	Scratched	291.00 FS	*232.40 FS
111	1		*WINDOW GUIDE TRIM STRIP - RH	Serviceable	242.00 FS	*- FS
112	1		*TYRE PRESSURE DATA PLATE	Necessary	27.00 FS	*21.12 FS
113	1		*NOISE INSULATION	Cracked	244.00 FS	*195.20 FS
114	1		*FRONT BUMPER REINFORCEMENT BEAM COVER PLATE	Bent	90.00 FS	*72.00 FS
115	1		*STEERING WHEEL AIRBAG UNIT	Activated	3,221.00 FS	*2,576.80 FS
116	1		*DASHBOARD AIRBAG	Activated	4,330.00 FS	*3,464.00 FS
117	2		*HEAD AIRBAG UNIT - LH / RH	Activated	3,512.00 FS	*2,809.60 FS
118	1		*KNEE AIRBAG UNIT	Activated	1,756.00 FS	*1,404.80 FS
119	2		*SEATBELT - LH / RH	Activated	2,080.00 FS	*1,664.00 FS
120	2		*SEAT BELT HEIGHT ADJUSTER	Bent	368.00 FS	*294.40 FS
121	1		*AIRBAG CONTROL UNIT	Activated	1,482.00 FS	*1,185.60 FS
122	3		*AIRBAG CRASH SENSOR	Activated	933.60 FS	*933.60 FS
123	1		*SPORTS STEERING WHEEL	Deformed	2,237.00 FS	*1,789.60 FS
124	1		*DASHBOARD	Cracked	4,014.00 FS	*3,211.20 FS
125	1		*LOUDSPEAKER COVER	Serviceable	88.00 FS	*- FS
126	1		*AIR VENT - CENTRE	Serviceable	142.00 FS	*- FS
127	1		*STOWAGE COMPARTMENT - RH	Serviceable	426.00 FS	*- FS
128	1		*MOULDED HEADLINER	Deformed	1,666.00 FS	*1,332.80 FS
129	1		*A-PILLAR TRIM - LH	Deformed	151.00 FS	*120.80 FS
130	1		*A-PILLAR TRIM - RH UPPER	Deformed	151.00 FS	*120.80 FS
131	2		*B-PILLAR TRIM - LH / RH	Serviceable	408.00 FS	*- FS
132	2		*C-PILLAR TRIM - LH / RH	Serviceable	284.00 FS	*- FS
133	2		*D-PILLAR TRIM - LH / RH	Serviceable	218.00 FS	*- FS
134	2		*FOLDING GRAB HANDLE - FRONT	Loose	266.00 FS	*212.80 FS
135	2		*FOLDING GRAB HANDLE - LH / RH REAR	Loose	266.00 FS	*212.80 FS
136	1		*ASSEMBLY CARRIER	Bent	962.00 FS	*769.60 FS
137	1		*SET BONDED RUBBER BUSHES	Necessary	93.00 FS	*74.32 FS
138	1		*TRACK CONTROL ARM	Bent	345.00 FS	*275.60 FS
139	1		*COMPLETE STABILIZER	Serviceable	380.00 FS	*- FS
140	1		*WHEEL BEARING HOUSING	Bent	555.00 FS	*443.60 FS
141	1		*WHEEL BEARING	Necessary	479.00 FS	*383.20 FS
142	1		*GUIDE JOINT - RH	Cracked	119.00 FS	*95.20 FS
143	1		*COUPLING ROD	Bent	90.00 FS	*71.36 FS
144	1		*GAS SHOCK ABSORBER	Bent	256.00 FS	*204.80 FS
145	1		*DRIVE SHAFT - RH	Bent	2,190.00 FS	*1,752.00 FS
146	1		*TRACK ROD	Bent	88.00 FS	*70.00 FS
147	1		*TIE ROD END - RH	Bent	121.00 FS	*96.40 FS
148	1		*STEERING GEAR	Bent	4,503.00 FS	*3,602.40 FS
149	1		*SET STEERING BOX REPAIR	Necessary	44.00 FS	*34.72 FS
150	1		*GEARBOX ASSEMBLY	Not Working	16,515.00 FS	*13,212.00 FS
151	1		*TRANSMISSION FLUID	Not Necessary	60.00 FS	*- FS
152	1		*FRONT ALUMINIUM RIM - RH	Cut	666.00 FS	*666.00 FS
153	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
154	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
155	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
156	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
157	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
158	1		*SUNDRIES	Necessary	1,000.00 FS	*515.04 FS
159	1		*UNDERBODY TRIM RHS FRONT (Supplementary)	Cracked	163.00 FS	*130.40 FS
160	1		*UNDERBODY TRIM COVER RHS FRONT (Supplementary)	Cracked	12.00 FS	*8.96 FS
161	1		*GEARBOX MOUNTING LHS (Supplementary)	Cracked	246.00 FS	*196.80 FS
162	1		*BATTERY CONSOLE (Supplementary)	Cracked	189.00 FS	*150.80 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
163	1		*SHOCK ABSORBER SUSPENSION STRUT STORAGE (Supplementary)	Necessary	117.00 FS	*93.20 FS
164	1		*SHOCK ABSORBER DEEP GROOVE BALL THRUST BEARING (Supplementary)	Necessary	44.00 FS	*34.72 FS
165	1		*SEAT CUSHION AIRBAG FRONT RHS (Supplementary)	Torn	1,428.00 FS	*1,142.40 FS
166	1		*BACKREST COVER FRONT RHS (Supplementary)	Torn	2,068.00 FS	*1,654.40 FS
167	1		*GEARBOX SELECTOR MECHANISM (Supplementary)	Serviceable	1,813.00 FS	*- FS
168	1		*CHASSIS DATA TAG ON LOWER A-PILLAR (Supplementary)	Necessary	436.00 FS	*348.40 FS
169	1		*COOLANT PIPE WITH INNER HEAT EXCHANGER (Supplementary)	Bent	471.00 FS	*376.40 FS
170	1		*TYRE FRONT RH (Supplementary)	Cut	335.00 FS	*335.00 FS
171	1		*WHEEL BEARING FRONT LHS (Supplementary)	Bent	479.00 FS	*383.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 115,225.60 78,149.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	800.00
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
5	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG	New	3,600.00	3,600.00
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS. RENEW ACCORDINGLY	New	2,800.00	2,800.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IN NECESSARY	New	2,400.00	2,400.00
8	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
9	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
10	TO PLACE VEHICLE ON CAR O-LINER	New	1,800.00	1,800.00
11	TO RENEW TURBOCHARGE AND OTHER ENGINE COMPARTMENT	New	980.00	0.00
12	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
13	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND TRANSFER RHS WING MIRROR ASSY	New	350.00	350.00
14	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS AND RHS FRONT DOOR. CUT OUT AND REWELD RHS FENDER TOP SUPPORT AND CLOSING ELEMENT AND RHS A-LOWER PILLAR. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	12,600.00	5,750.00
15	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, RHS A-PILLAR, ENGINE COMPARTMENT, RHS FRONT FENDER TOP SUPPORT AND RHS FRONT DOOR. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	7,200.00	3,850.00
16	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE-REPAIR WHEEL ALIGNMENT CHECK AND POST-REPAIR WHEEL ALIGNMENT CHECK	New	520.00	520.00
17	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
18	TO REPAIR CHASSIS MEMBER RHS (Supplementary)	New	700.00	500.00
19	TO RESPRAY CHASSIS MEMBER RHS (Supplementary)	New	1,050.00	550.00
20	TO REMOVE AND RENEW RHS FRONT BACKREST COVER (Supplementary)	New	780.00	780.00
21	TO RENEW GEAR ASSY AND CARRY OUT ADAPTATION (Supplementary)	New	1,800.00	1,800.00
Gross Labour Cost (\$\$)			40,764.00	28,604.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >