

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20004481/KEA3Q2

**Date:** 19/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLX6024Z **Insured Vehicle No :** GBF6987H

**Date of Loss:** 17/03/2020 **Nature of Claim:** TP **Claim No:** 4359392135SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLX6024Z</b>		
Make & Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)	Engine No:	P520495587
Reg. Date:	02/04/2018 (Man. Year: 2017)	Chassis No:	JM6BN22A8J0205301
Colour:	Metallic Blue	Odometer:	14067 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,185.36	5,006.16	1,179.20	19.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	720.00	510.00	41.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,415.36</b>	<b>5,726.16</b>	<b>1,689.20</b>	<b>22.78</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>519.08</b>	<b>400.83</b>	<b>118.25</b>	<b>22.78</b>
<b>Nett Amount (S\$)</b>	<b>7,934.44</b>	<b>6,126.99</b>	<b>1,807.45</b>	<b>22.78</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 25/03/2020 Inspected At:

Chew Goon Motor (AMK)  
Blk 10 Ang Mo Kio Industrial Park 2A,  
#01-15/16 & 17, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Dented	1,215.80 FL	*1,215.80 FL
2	12		*FRONT BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
3	1		*FRONT BUMPER BRACKET RH	Not Necessary	30.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	540.00 FL	*- FL
5	1		*FRONT BUMPER BEAM (PLASTIC)	Not Necessary	260.00 FL	*- FL
6	1		*FRONT BUMPER TOP RETAINER RH	Distorted	16.20 FL	*16.20 FL
7	1		*FRONT BUMPER SIGNAL LAMP RH	Cut	159.00 FL	*159.00 FL
8	1		*FRONT BUMPER SIGNAL LAMP CHROME MOULDING	Dented	75.00 FL	*75.00 FL
9	1		*FRONT BUMPER FOG LAMP	Cut	663.10 FL	*663.10 FL
10	1		*FRONT BUMPER FOG LAMP COVER	Scratched	24.00 FL	*24.00 FL
11	1		*FRONT BUMPER CORNER RETAINER RH	Distorted	17.00 FL	*17.00 FL
12	1		*FRONT BUMPER UPPER CORE	Serviceable	355.00 FL	*- FL
13	1		*HEADLAMP RH (LED)	Cracked	3,788.60 FL	*3,788.60 FL
14	1		*FRONT GRILLE	Cracked	145.00 FL	*145.00 FL
15	1		*FRONT GRILLE SIDE CHROME MOULDING RH	Serviceable	210.00 FL	*- FL
16	1		*WIPER TANK	Bent	118.00 FL	*118.00 FL
17	1		*WIPER TANK MOTOR	Not Necessary	79.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)**    **7,731.70**    **6,257.70**  
**- List Item Discount on L Items 20.00/20.00% (\$\$)**    1,546.34    1,251.54

**Total Parts (\$\$)**    **6,185.36**    **5,006.16**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF O/S FENDER ,HEADLAMP PANEL AND PARTS REPLACEMENT	New	600.00	300.00
3	TO RESPRAY AFFECTED AREAS	New	600.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,230.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >