

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date 12/11/2020 Reference CC4/FCI20

Reference

INV No.

CC4/FCI20004486/Kea3q2

Code FCI2



AC2007618

PROFESSIONAL SERVICE FEE

Vehicle No. GBB 7364U

Insured Veh. SHC 733H

Claim No. D20001634MFSH

Policy No. D-20094921MFSH

Accident Date 23/03/2020

Inspection Date 25/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile					
MS F	MS FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20004486/Kea3q2				
	OBINSON ROAD 11 CITY HOUSES	INGAPORE 068877	Date: 12-11-2020 Code: FCI2		
1.		Policy Particulars	- THIRD PARTY CLAIM		
	Insured Veh.	SHC 733H	Veh. Inspected	GBB 7364U	
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
	Claim No.	D20001634MFSH	Excess (\$)	0.00	
	Assign From	MERINA CHIA	Assign Date	25/03/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA HIACE (M)	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	JTFHT02PX00052361	Colour	WHITE	
	Odometer	479716	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
	L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
	R/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm	
	L/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR N/S PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	23/03/2020	Inspection Date	25/03/2020	
	Survey held at	K KIM HIN AUTOMOTIVE PTE L	TD		
		160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 7364U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	415.00	415.00
1	N/S REAR BUMPER SIDE RETAINER	DISTORTED	30.00	30.00
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
2	REAR BUMPER LOWER BRACKET @\$30.00	N/S BENT	60.00	30.00
1	N/S TAILLAMP	CRACKED	300.80	300.80
1	N/S TAILLAMP PANL	NOT NECESSARY	248.00	-
1	N/S TAILLAMP LOWER APRON GARNISH	CRACKED	100.00	100.00
1	TAILGATE	BENT	2,150.00	2,150.00
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	275.00	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	395.00	-
1	TAILGATE LOGO	NECESSARY	55.00	55.00
1	REAR END PANEL-OUTER	BENT	331.70	331.70
	LESS 25% DISCOUNT		-1,100.13	-863.13
			3,300.37	2,589.37
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR ASSY (SN)	DENTED	220.00	200.00
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE "6 PAX" STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE GLASS DAMPING SEAL (SN)	NECESSARY	20.00	20.00
			310.00	290.00
	LABOUR			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK.		1,000.00	800.00
	TO REMOVE AND RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	120.00
	TO TRANSFER TAILGATE'S FITTINGS.		80.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		60.00	50.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		800.00	680.00

Report Ref No. CC4/FCI20004486/Kea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION.		30.00	20.00
			2,090.00	1,730.00
	GRAND TOTAL		5,700.37	4,609.37

RECOMMENDED COST OF LUMP SUM REPAIRS		3,650.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/FCI20004486/Kea3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 7364U

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315



