

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20004504/QBA3Q2

**Date:** 25/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700039955

**Claimant**  
**Vehicle No :** TIB1241Y **Insured Vehicle No :** SKC2977Y

Date of Loss: 20/03/2020 Nature of Claim: TP Claim No: 0567534152SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	TIB1241Y	Engine No:	44797710082899
Make & Model:	MERCEDES-BENZ 0405G, 12.0 D (A)	Chassis No:	WEB61232321099676
Reg. Date:	14/11/2003 (Man. Year: 2002)	Odometer:	976236 km
Colour:	Multi-colour		
Engine Capacity:	11967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,149.00	792.00	357.00	31.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,149.00</b>	<b>792.00</b>	<b>357.00</b>	<b>31.07</b>
<b>+ Loss of Use (3.0 x S\$250.00/day) (S\$)</b>		750.00		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>1,549.00</b>		

### INSPECTION

Date of Assignment: 25/03/2020

Date Inspected: 25/03/2020 Inspected At:

Smrt Automotive Services Pte Ltd  
(HQ)  
No. 61 Woodlands Industrial Park E9,  
#04-04 Premium Building  
Singapore 757047

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	354.00	262.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,149.00</b>	<b>792.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >