

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004505/ATF3E2

Date: 24/08/2020

REFERENCE

Insured/Claimant: SIM HUA SOON SHEN HUASHUN Policy No: 2070036793
Date of Loss: 23/03/2020 Nature of Claim: OD Claim No: 4766507645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU2230X**
Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC38104
Reg. Date: 19/03/2020 (Man. Year: 2019) Chassis No: WAUZZZ8V3LA034964
Colour: Red Odometer: 207 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$118,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,610.00	4,821.20	5,788.80	54.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,194.00	2,902.00	2,292.00	44.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,804.00	7,723.20	8,080.80	51.13
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,204.00	7,123.20	8,080.80	53.15
+ GST 7.00/7.00% (S\$)	1,064.28	498.62	565.66	53.15
Nett Amount (S\$)	16,268.28	7,621.82	8,646.46	53.15

INSPECTION

Date of Assignment: 25/03/2020
Date Inspected: 25/03/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	1,756.00 FS	*- FS	
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS	
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS	
4	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	280.00 FS	*- FS	
5	1		*FRONT FENDER - RH	Buckled	802.00 FS	*641.20 FS	
6	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	68.00 FS	*- FS	
7	1		*LED HEADLIGHT - RH	Cracked	5,193.00 FS	*4,154.40 FS	
8	1		*LED WITH HEAT SINK - RH	Not Necessary	689.00 FS	*- FS	
9	1		*MAIN LIGHT ELECTRONICS POWER MODULE - RH	Not Necessary	714.00 FS	*- FS	
10	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	524.00 FS	*- FS	
11	1		*HEADLIGHT HOSE - RH	Not Necessary	38.00 FS	*- FS	
12	1		*LIFT CYLINDER - RH	Not Necessary	134.00 FS	*- FS	
13	1		*SUNDRIES	Necessary	200.00 FS	*25.60 FS	
					Total Parts (\$)	10,610.00	4,821.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK	New	384.00	192.00
			Gross Labour Cost (S\$)	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >