

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004508/AKA3N2

Date: 21/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800049160

Claimant
Vehicle No : YP4550Y **Insured Vehicle No :** SBM9228J

Date of Loss: 23/03/2020 Nature of Claim: TP Claim No: 7315373304SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4550Y		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C32659
Reg. Date:	14/10/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20959
Colour:	White	Odometer:	73180 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,608.00	2,951.25	2,656.75	47.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	810.00	1,470.00	64.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,888.00	3,761.25	4,126.75	52.32
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	7,888.00	3,000.00	4,888.00	61.97
+ GST 7.00/7.00% (S\$)	552.16	210.00	342.16	61.97
Nett Amount (S\$)	8,440.16	3,210.00	5,230.16	61.97
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,612.00		
Global Sum Settlement (S\$)		3,600.00		

INSPECTION

Date of Assignment: 25/03/2020

Date Inspected: 25/03/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@KakiBukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H CORNER PANEL	Cracked	506.00 F	*506.00 FL
2	1		*FRONT R/H HEAD LAMP	Cracked	501.00 F	*501.00 FL
3	1		*FRONT R/H SIGNAL LAMP	Cracked	266.00 F	*266.00 FL
4	1		*FRONT R/H SIDE LAMP	Cracked	251.00 F	*251.00 FL
5	1		*FRONT BUMPER	Not Necessary	1,060.00 F	*- FL
6	1		*FRONT R/H BUMPER SIDE COVER	Cut	341.00 F	*341.00 FL
7	1		*FRONT R/H DOOR	Dented	2,070.00 F	*2,070.00 FL
8	1		*FRONT R/H STEP PANEL	Not Necessary	613.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,608.00	3,935.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	983.75
Total Parts (S\$)	5,608.00	2,951.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT R/H DOOR AND DOOR COMPONENTS	New	280.00	80.00
2	TO CHECK WIRING	New	100.00	30.00
3	TUFF KOTE	New	100.00	0.00
4	PANEL BEATING	New	800.00	350.00
5	SPRAY PAINTING	New	1,000.00	350.00
Gross Labour Cost (\$\$)			2,280.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >