



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 1923M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT GS4 (SN)	TO REPAIR SEE LABOUR	1,182.60	-
1	FOG LAMP MOULDING OU (SN)	NOT NECESSARY	192.70	-
1	FOG LAMP COVER CHORM (SN)	NOT NECESSARY	192.70	-
1	BUMPER LOWER FRT GS4 (SN)	NOT NECESSARY	395.90	-
1	BUMPER BRACKET FRT L (SN)	NOT NECESSARY	113.90	-
1	BUMPER BRACKET FRT R (SN)	NOT NECESSARY	113.90	-
1	ALLOY RIM 20"INCH GS (SN)	CUT	1,068.60	990.63
1	TYRE PRESSURE SENSOR (SN)	NECESSARY	117.30	108.81
			3,377.60	1,099.44
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER,ETC.INCLUSIVE OF THE REPAIR OF BUMPER FRT GS4.		1,600.00	450.00
	TO PUTTY AND SPRAY PAINT ON FRONT BUMPER,ETC.		1,400.00	400.00
	TO REPLACE LHF RIM.		50.00	50.00
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT.		280.00	280.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.	NOT NECESSARY	375.00	-
			3,705.00	1,180.00
	GRAND TOTAL		7,082.60	2,279.44
	RECOMMENDED COST OF REPAIRS			2,279.44

Report Ref No. CS/AWA20004511/R1sf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.