

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Mar 2020		25 Mar 2020 19:07 Edit Adj Rpt	S\$6,550.00 Edit Estimates	S\$6,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	CHOON HUAT ENGINEERING PTE LTD , Co. Reg. No.: 198306049R								
Main Claimant:	DEFINE LEASING PTE LTD , Co. Reg. No.: 201828674Z								
Vehicle Reg. No.:	SMP7200E	Date of Loss:	23/03/2020 00:00 - :59 [5 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D201483C02	Policy/Cover Note No.:	DMCVSN30373419033 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBB8344X	Policy No. (Claimant):	5115502938-000021CLASSIC						
		Excess:	S\$0.00						
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/04/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMP7200E (SNM20D201483C02)**
[GBB8344X]
TP
DEFINE LEASING PTE LTD
Mar 23 2020 12:00AM
[CHOON HUAT ENGINEERING PTE LTD]
RICO 60 AUTO SERVICES PTE LTD

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#) ▼

Photos/Images					
3 per page ▼					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/03/20 13:08	Chassis Number		Load JPG	☒
2	26/03/20 13:09	Odometer Reading		Load JPG	☒
3	26/03/20 13:09	General View		Load JPG	☒
4	26/03/20 13:09	General View		Load JPG	☒
5	26/03/20 13:09	General View		Load JPG	☒
6	26/03/20 13:09	General View		Load JPG	☒
7	26/03/20 13:09	General View		Load JPG	☒
8	26/03/20 13:09	General View		Load JPG	☒
9	26/03/20 13:09	General View		Load JPG	☒
10	26/03/20 13:09	General View		Load JPG	☒
11	26/03/20 13:09	General View		Load JPG	☒
12	26/03/20 13:09	General View		Load JPG	☒
13	26/03/20 13:09	General View		Load JPG	☒
14	26/03/20 13:09	General View		Load JPG	☒
15	26/03/20 13:09	General View		Load JPG	☒
16	26/03/20 13:09	General View		Load JPG	☒
17	26/03/20 13:09	General View		Load JPG	☒
18	26/03/20 13:09	General View		Load JPG	☒
19	26/03/20 13:09	General View		Load JPG	☒
20	26/03/20 13:09	General View		Load JPG	☒
21	26/03/20 13:09	General View		Load JPG	☒
22	26/03/20 13:09	General View		Load JPG	☒
23	26/03/20 13:09	General View		Load JPG	☒
24	26/03/20 13:09	General View		Load JPG	☒
25	26/03/20 13:09	General View		Load JPG	☒
26	26/03/20 13:09	General View		Load JPG	☒
27	26/03/20 13:09	General View		Load JPG	☒
28	26/03/20 13:09	General View		Load JPG	☒
29	26/03/20 13:09	General View		Load JPG	☒
30	26/03/20 13:09	General View		Load JPG	☒
31	26/03/20 13:09	General View		Load JPG	☒
32	26/03/20 13:09	General View		Load JPG	☒
33	26/03/20 13:09	General View		Load JPG	☒
34	26/03/20 13:09	General View		Load JPG	☒
35	26/03/20 13:09	General View		Load JPG	☒
36	26/03/20 13:09	General View		Load JPG	☒
37	26/03/20 13:09	General View		Load JPG	☒
38	26/03/20 13:09	General View		Load JPG	☒
39	26/03/20 13:09	General View		Load JPG	☒
40	26/03/20 13:09	General View		Load JPG	☒

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	26/03/20 13:09	General View		Load JPG	☒
42	26/03/20 13:09	General View		Load JPG	☒
43	26/03/20 13:09	General View		Load JPG	☒
44	26/03/20 13:09	General View		Load JPG	☒
45	26/03/20 13:09	General View		Load JPG	☒
46	27/03/20 20:29	Reinspection Photo		Load JPG	☒
47	27/03/20 20:29	Reinspection Photo		Load JPG	☒
48	27/03/20 20:29	Reinspection Photo		Load JPG	☒
49	27/03/20 20:29	Reinspection Photo		Load JPG	☒
50	27/03/20 20:29	Reinspection Photo		Load JPG	☒
51	27/03/20 20:29	Reinspection Photo		Load JPG	☒
52	27/03/20 20:29	Reinspection Photo		Load JPG	☒
53	27/03/20 20:29	Reinspection Photo		Load JPG	☒
54	27/03/20 20:29	Reinspection Photo		Load JPG	☒
55	27/03/20 20:29	Reinspection Photo		Load JPG	☒
56	27/03/20 20:29	Reinspection Photo		Load JPG	☒
57	27/03/20 20:29	Reinspection Photo		Load JPG	☒
58	27/03/20 20:29	Reinspection Photo		Load JPG	☒
59	27/03/20 20:29	Reinspection Photo		Load JPG	☒
60	27/03/20 20:29	Reinspection Photo		Load JPG	☒
61	27/03/20 20:29	Reinspection Photo		Load JPG	☒
62	27/03/20 20:29	Reinspection Photo		Load JPG	☒
63	27/03/20 20:29	Reinspection Photo		Load JPG	☒
64	27/03/20 20:29	Reinspection Photo		Load JPG	☒
65	27/03/20 20:29	Reinspection Photo		Load JPG	☒
66	27/03/20 20:29	Reinspection Photo		Load JPG	☒
67	27/03/20 20:29	Reinspection Photo		Load JPG	☒
68	27/03/20 20:29	Reinspection Photo		Load JPG	☒
69	27/03/20 20:29	Reinspection Photo		Load JPG	☒
70	27/03/20 20:29	Reinspection Photo		Load JPG	☒
71	27/03/20 20:29	Reinspection Photo		Load JPG	☒
72	27/03/20 20:29	Reinspection Photo		Load JPG	☒
73	27/03/20 20:29	Reinspection Photo		Load JPG	☒
74	27/03/20 20:29	Reinspection Photo		Load JPG	☒
75	27/03/20 20:29	Reinspection Photo		Load JPG	☒
76	02/04/20 08:12	After Repair Photo		Load JPG	☒
77	02/04/20 08:12	After Repair Photo		Load JPG	☒
78	02/04/20 08:12	After Repair Photo		Load JPG	☒
79	02/04/20 08:12	After Repair Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/03/20 19:07	PRS EMAIL		Load HTM	
2	25/03/20 19:07	OI REPORT		Load PDF	
3	25/03/20 19:07	TP REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20004524/UTF3S2**Date:** 15/04/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30373419033
Claimant Vehicle No :	SMP7200E	Insured Vehicle No :	GBB8344X
Date of Loss:	23/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201483C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7200E		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0D70497
Reg. Date:	11/10/2019 (Man. Year: 2019)	Chassis No:	ZWR800388395
Colour:	White	Odometer:	80639 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,341.25	6,214.72	14,126.53	69.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,630.00	1,990.00	4,640.00	69.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,971.25	8,204.72	18,766.53	69.58
Approved Total (Overridden) (\$\$)		6,550.00		
(\$\$)	26,971.25	6,550.00	20,421.25	75.71
+ GST 7.00/7.00% (\$\$)	1,887.99	458.50	1,429.49	75.71
Nett Amount (\$\$)	28,859.24	7,008.50	21,850.74	75.71

INSPECTION

Date of Assignment:	25/03/2020	
Date Inspected:	26/03/2020 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Apr 2020)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMP7200E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	489.00 FL	*185.10 FL
2	1		*REAR TAILGATE	Badly Dented	1,649.00 FL	*1,649.00 FL
3	2		*REAR TAILGATE LAMP L+R	Not Necessary	1,048.00 FL	*- FL
4	1		*REAR TAILGATE CENTER CHROME	Not Necessary	869.00 FL	*- FL
5	1		*REAR TAILGATE CENTER CHROME LOGO	Not Necessary	97.00 FL	*- FL
6	2		*REAR TAILGATE LICENCE PLATE LAMP L+R	Not Necessary	136.00 FL	*- FL
7	1		*REAR TAILGATE OPENER	Not Necessary	671.00 FL	*- FL
8	1		*REAR TAILGATE EMBLEM	Necessary	107.00 FL	*85.10 FL
9	1		*REAR TAILGATE INNER TRIM BOTTOM	Deformed / Torn	979.00 FL	*699.10 FL
10	2		*REAR TAILGATE HINGE L+R	Not Necessary	276.00 FL	*- FL
11	2		*REAR TAILGATE ABSORBER L+R	Not Necessary	876.00 FL	*- FL
12	1		*REAR TAILGATE LOCK	Dented / Shorted	1,071.00 FL	*561.10 FL
13	1		*REAR TAILGATE LOCK CATCH	Not Necessary	89.00 FL	*- FL
14	1		*REAR TAILGATE AUTO GATE (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*REAR BUMPER	Dented / Deformed	1,459.00 FL	*1,025.00 FL
16	2		*REAR BUMPER L+R	Deformed / Torn	1,246.00 FL	*900.00 FL
17	1		*REAR BUMPER REFLECTOR L+R	O/s Cracked	648.00 FL	*97.00 FL
18	1		*REAR BUMPER RETAINER L+R	O/s Bent	456.00 FL	*115.00 FL
19	2		*REAR BUMPER BRACKET L+R	Not Necessary	602.00 FL	*- FL
20	1		*REAR BUMPER REINFORCEMENT BAR	No such part	879.00 FL	*- FL
21	1		*REAR BUMPER SPONGE	No such part	674.00 FL	*- FL
22	1		*REAR BUMPER SIDE (NPA)	Repeated	0.00 FL	*- FL
23	2		*REAR BUMPER SIDE RETAINER L+R (NPA)	Repeated	0.00 FL	*- FL
24	1		*END PANEL	Badly Dented	1,783.00 FL	*899.50 FL
25	1		*END PANEL TOP GARNISH	Twisted	451.00 FL	*245.30 FL
26	1		*FLOOR PANEL	Repair	1,819.00 FL	*- FL
27	1		*FLOOR PANEL TOP BOARD	Warped / Dented	1,879.00 FL	*1,425.10 FL
28	1		*REAR EXHAUST PIPE	Not Necessary	961.00 FL	*- FL
29	2		*REAR EXHAUST MOUNTING	Not Necessary	172.00 FL	*- FL
30	1		*REAR FLOOR PANEL INNER TRIM	Not Necessary	941.00 FL	*- FL
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	936.00 FS	*200.00 FS
32	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
33	1		*REVERSE SENSOR	Repeated	500.00 FS	*- FS
34	1		*REVERSE CAM	Not Necessary	1,200.00 FS	*- FS
35	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
36	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
37	10		*REAR BUMPER CLIPS	Necessary	120.00 FS	*50.00 FS
38	10		*REAR FENDER COWLING CLIPS	Not Necessary	120.00 FS	*- FS
39	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
40	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
41	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,923.00	8,186.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,581.75	1,971.58

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					20,341.25	6,214.72
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN.	New	2,400.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	1,800.00	1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	120.00	60.00
4	TO RNR REAR WINDSCREEN.	New	800.00	120.00
5	TO RNR REAR BOT MECHANISM.	New	120.00	60.00
6	TO RNR REAR LUGGAGE COMPARTMENT.	New	400.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	New	300.00	50.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	New	250.00	0.00
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION.	New	200.00	20.00
10	TO DO DIAGNOSTIC AND RESET, REPROGRAM OR CODING FAULT CODE.	New	120.00	0.00
11	TO DO WATER LEAK TEST.	New	120.00	0.00
Gross Labour Cost (\$)			6,630.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >