

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

(S/CTI 20004533) VED 3

CTI/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) Typ: st

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 3,500/- 45)

N/S	O/S

26/3/20 Cont. and 1/5 @ 3500 with AA chnee
C \$ 10,613.20 Red - 75%

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

China Taiping Insurance (S) Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Attn: motor claims Dept

23/3/2020

not Allowed
26/3/20
2/5# 3500
Hdy s.

Estimate cost of repair vehicle no: SFA6733C

Trunk lid

2pcs Trunk light \$369.40x2

Trunk lid lock

Trunk lid emblem

Trunk lid rubber

Trunk lid emblem '520I'

Booth lid inner trim

2pcs tail lamp \$625.45

2pcs tail lamp gutter strip \$41.05

Trunk lid tail panel

Tail panel inner garnish

Rear bumper

Rera bumper lower guide

Rear bumper adapter

Rear bumper lower inner garnish

Rear exhaust tail pipe chrome

Rear bumper tow cover

Rear bumper center bracket

2pcs rear bumper reflectors \$37.75x2

Rear bumper reinforcement

2pcs rear bumper side bracket \$293.15x2

4pcs rear bumper PDC sensor \$370x4 195x2=390

Rear exhaust silencer

2pcsRear exhaust Rubber ring \$19.70x2

1 set 12pcsRear bumper \$1.70x12 c/p

1 set 20pcs Blind rivet \$1.35

20pcs expanding nut \$1.15x20

R	1650.65	X
11	738.80	X
11	218.20	X
11	71.60	—
11	83.00	2
11	64.45	—
11	170.50	X
11	1250.90	X
11	82.10	X
R	821.40	X
11	116.15	X
11	1571.95	—
11	58.25	—
11	109.35	2
11	145.80	2
R	135.80	X
11	47.85	X
11	67.45	2
11	75.50	X
11	775.95	2
11	586.30	X
11	1480.00	2 p.c.s.
11	1224.25	X
11	39.40	X
11	20.40	—
11	27.00	—
11	23.00	X

52

Labour

Labour for knocking, welding, repair, replacement of parts

To spray painting

To apply rust-proofing

To remove/renew silencer box

To remove/renew PDC sensors

To program PDC Sensor

To checking wire

To sealing tail panel

1000.00 580

1200.00 600

11 200.00 X

11 150.00 X

150.00 50

180.00

80.00 20

11 80.00 X

14113.20

14696

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-3301
502
3135.95
4385.95
7508