



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007619
INV Date 12/11/2020
Reference CC4/FCI20004553/Uba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. GBB 1219X
Insured Veh. SHA 7997C
Claim No. D20001604MFSH
Policy No. D-20094922MFSH
Accident Date 19/03/2020
Inspection Date 25/03/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20004553/Uba3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-11-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7997C	Veh. Inspected	GBB 1219X	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20001604MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	25/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTFHT02P900024891	Colour	WHITE	
Odometer	325660	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	KENDA	6 mm	
L/H Front Tyre	195 R15	KENDA	6 mm	
R/H Rear Tyre	195 R15	KENDA	6 mm	
L/H Rear Tyre	195 R15	KENDA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2020	Inspection Date	25/03/2020	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 1219X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BADLY DENTED	1,850.00	1,850.00
1	REAR TAILGATE RUBBER	NOT NECESSARY	387.90	-
1	REAR TAILGATE LOCK	DENTED / JAMMED	359.00	359.00
1	REAR NUMBER PLATE OUTER GARNISH	NOT NECESSARY	346.50	-
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	165.30	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR TAILGATE "TOYOTA LOGO" MOTIF	NECESSARY	70.50	70.50
1	REAR TAIL LAMP RH	CRACKED	365.10	365.10
1	REAR CORNER PANEL RH	TO REPAIR SEE LABOUR	165.80	-
1	REAR CORNER PANEL GARNISH BRACKET	NOT NECESSARY	31.50	-
1	REAR TAILGATE WINDSCREEN MOULDING	NO SUCH PARTS	285.90	-
1	REAR BUMPER	DISTORTED	496.50	496.50
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
4	REAR BUMPER BRACKET	BENT	404.00	100.00
1	REAR END PANEL INNER	BADLY DENTED	936.20	845.20
1	REAR END PANEL OUTER	BADLY DENTED	566.10	566.10
1	REAR SPARE TYRE CARRIER	BENT	250.60	250.60
1	REAR EXHAUST PIPE	NOT NECESSARY	971.10	-
2	REAR EXHAUST PIPE MOUNTING @\$42.50	NOT NECESSARY	85.00	-
	LESS 25% DISCOUNT		-	-1,237.75
			7,835.00	3,713.25
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	15.00	10.00
1	REAR NUMBER PLATE (METAL PLATE)(SN)	NOT NECESSARY	35.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	45.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR "COMPANY ADVERTISEMENT" STICKER (SN)	NECESSARY	350.00	150.00
			715.00	400.00

Report Ref No. CC4/FCI20004553/Uba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE AND REFIX REAR BUMPER DISTANCE SENSOR.		90.00	50.00
	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM.		80.00	60.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	20.00
	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS.	NOT NECESSARY	200.00	-
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC.S.INCLUSIVE OF THE REPAIR OF REAR CORNER PANEL RH.		1,000.00	800.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		800.00	700.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	60.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS.		120.00	120.00
			2,470.00	1,810.00
	GRAND TOTAL		11,020.00	5,923.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CC4/FCI20004553/Uba3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 1219X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 1219X

RE-INSPECTION

