

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004554/R1EA3Q2

Date: 28/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497200

Claimant
Vehicle No : SMN2534K **Insured Vehicle No :** SLK5447L

Date of Loss: 25/03/2020 Nature of Claim: TP Claim No: 5680710234SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN2534K		
Make & Model:	BMW X1, 1.5 SDRIVE 18i (A)	Engine No:	42595657B38B15A
Reg. Date:	30/07/2019 (Man. Year: 2019)	Chassis No:	WBAJG120005N60815
Colour:	Brown	Odometer:	17533 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,143.15	963.25	5,179.90	84.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,686.00	3,293.00	2,393.00	42.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,829.15	4,256.25	7,572.90	64.02
+ GST 7.00/7.00% (\$\$)	828.04	297.94	530.10	64.02
Nett Amount (\$\$)	12,657.19	4,554.19	8,103.00	64.02
+ Loss of Use (4.0 x S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,796.19		

INSPECTION

Date of Assignment: 20/04/2020

Date Inspected: 20/04/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*BRIDGESTONE 225/55 17 097Y ER3 00*RFT (1 PCS) LEFT FRONT	Not Necessary	455.00 FS	*- FS
3	1		*ALLOY RIM 7.5X17 V SPK 560	Not Necessary	814.00 FS	*- FS
4	1		*HUB CAP WITH CHROME EDGE	Not Necessary	29.40 FS	*- FS
5	1		*BRACKET FOR	Not Necessary	39.55 FS	*- FS
6	1		*FRT LH DOOR	Repair	1,203.80 FS	*- FS
7	1		*LH CROSS SUPPORT SIDE PANEL	Not Necessary	67.95 FS	*- FS
8	1		*LH WHEEL HOUSING STRUT EXTENSION	Not Necessary	152.25 FS	*- FS
9	1		*LH COLUMN A SIDE PANEL BRACKET	Not Necessary	35.10 FS	*- FS
10	1		*FRT LH SIDE PANEL	Bent	664.00 FS	*664.00 FS
11	1		*BRACKET SIDE PANEL COLUMN A	Not Necessary	35.10 FS	*- FS
12	1		*HOLDER	Not Necessary	35.10 FS	*- FS
13	1		*LH UPPER FRT DOOR HINGE	Not Necessary	56.30 FS	*- FS
14	1		*LH LOWER FRT DOR HINGE	Not Necessary	56.30 FS	*- FS
15	1		*LH DOOR SILL MOUNT COVER	Not Necessary	22.35 FS	*- FS
16	1		*LH OUTSIDE MIRROR COVER CAP PRIMED	Not Necessary	122.00 FS	*- FS
17	1		*LH SUPPORTING RING	Scratched	53.45 FS	*53.45 FS
18	1		*LH LOWER HOUSING SECTION	Not Necessary	25.15 FS	*- FS
19	1		*LH EXTERIOR MIRROR W/O MOUNTING PAR	Not Necessary	485.40 FS	*- FS
20	1		*LH ADDITIONAL TURN INDICATOR LAMP	Not Necessary	59.35 FS	*- FS
21	1		*FRT DOOR BRAKE	Not Necessary	77.45 FS	*- FS
22	1		*CHANNEL SEAL	Not Necessary	76.10 FS	*- FS
23	1		*SEAL ,OUTER	Not Necessary	27.80 FS	*- FS
24	1		*COVER ,WINDO	Not Necessary	94.60 FS	*- FS
25	1		*FRT LH DOOR EXTERIOR CHANNEL COVER	Not Necessary	137.35 FS	*- FS
26	1		*FRT LH DOR WINDOW FRAME COVER (ALU)	Not Necessary	94.60 FS	*- FS
27	1		*FRT LH DOOR WINDOW GUIDE	Not Necessary	122.60 FS	*- FS
28	1		*SEAL TRIM	Not Necessary	21.90 FS	*- FS
29	1		*FOAM PAD ,DO	Not Necessary	4.15 FS	*- FS
30	1		*FRT LH WONDOW LIFTER W/MOTOR	Not Necessary	315.10 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*CRASHPAD ,DO	Not Necessary	35.70 FS	*- FS
32	1		*SOUND INSULA	Not Necessary	84.10 FS	*- FS
33	1		*CRASHPAD ,DO	Not Necessary	35.70 FS	*- FS
34	1		*FRT DOOR EDGE PROTECTION	Not Necessary	171.85 FS	*- FS
35	1		*FRT LH DOOR JOINT SEAL	Not Necessary	59.45 FS	*- FS
36	1		*FRT LH DOOR JOINT SEALING ENTRANCE	Not Necessary	34.95 FS	*- FS
37	1		*EXPANDING RIVET BLACK (26 PCS)	Necessary	36.40 FS	*14.00 FS
38	1		*FRT LH WHEEL ARCH TRIM	Scratched	151.80 FS	*151.80 FS
Total Parts (S\$)					6,143.15	963.25

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE LEFT FRONT DOOR ,LEFT FRONT SIDE FENDER ,LEFT MIRROR ASSEMBLY INCLUDE REMOVE ATTACH MENT ETC	New	2,550.00	1,700.00
2	SPRAY PAINTING LEFT MIRROR COVER ,LEFT FRONT DOOR AND LEFT FRONT FENDER	New	1,567.00	1,343.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (2 PANEL)	New	236.00	100.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDCUT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	0.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	0.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING LEFT FRONT	New	94.00	0.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$)			5,686.00	3,293.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >