

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20004558/AGA3Q2
Date: 02/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100278401-08
Claimant Vehicle No :	SMN7880C	Insured Vehicle No :	SKC8415M
Date of Loss:	17/03/2020	Nature of Claim:	TP
		Claim No:	8854290232SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7880C		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC32348
Reg. Date:	28/08/2019 (Man. Year: 2019)	Chassis No:	WAUZZZGA2KA079147
Colour:	Grey	Odometer:	16295 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,552.00	470.40	2,081.60	81.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,672.00	1,522.00	1,150.00	43.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,224.00	1,992.40	3,231.60	61.86
+ GST 7.00/7.00% (S\$)	365.68	139.47	226.21	61.86

Nett Amount (S\$)	5,589.68	2,131.87	3,457.81	61.86
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,433.87		

INSPECTION

Date of Assignment: 31/03/2020

Date Inspected: 31/03/2020

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,108.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	73.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	268.00 FS	*214.40 FS
4	1		*REAR LIGHT REFLECTOR -RH	Not Necessary	28.00 FS	*- FS
5	1		*REAR BUMPER CARRIER	Not Necessary	517.00 FS	*- FS
6	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	24.00 FS	*- FS
7	1		*REAR PARKING AID SENSOR -OUTER (NPA)	Not Necessary	0.00 FS	*- FS
8	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
9	2		*REAR WHEEL COVER -LH/RH	Necessary	320.00 FS	*256.00 FS
10	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	2,552.00
						470.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,672.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >