

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004567/EQF3E2

Date: 25/08/2020

REFERENCE

Insured/Claimant: KOH CHEE HWEE, JEFFERY

Policy No: 1800145592

Date of Loss: 20/03/2020

Nature of Claim: OD

Claim No: 8610081475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG1822Y**

Make & Model: AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)

Engine No: CZE846849

Reg. Date: 07/12/2018 (Man. Year: 2018)

Chassis No: WAUZZZ8V3K1008346

Colour: Blue

Odometer: 28917 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$101,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,943.00	6,925.84	6,017.16	46.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,194.00	3,094.00	2,100.00	40.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,137.00	10,019.84	8,117.16	44.75
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	17,537.00	9,419.84	8,117.16	46.29
+ GST 7.00/7.00% (\$\$)	1,227.59	659.39	568.20	46.29
Nett Amount (\$\$)	18,764.59	10,079.23	8,685.36	46.29

INSPECTION

Date of Assignment: 27/03/2020

Date Inspected: 26/03/2020 Inspected At:

281 ALEXANDRA ROAD

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,894.00 FS	*1,515.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	36.00 FS	*28.64 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	505.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	280.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	153.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	177.00 FS	*- FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	681.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	178.00 FS	*- FS
11	1		*FRONT FENDER - LH	Dented	802.00 FS	*641.20 FS
12	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	68.00 FS	*- FS
13	1		*FRONT FENDER BRACE	Not Necessary	90.00 FS	*- FS
14	1		*WHEEL HOUSING LINER SEAL - LH	Not Necessary	32.00 FS	*- FS
15	1		*WHEEL HOUSING LINER - LH	Not Necessary	159.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
17	1		*LED HEADLIGHT - LH	Broken	5,193.00 FS	*4,154.40 FS
18	1		*MAIN LIGHT ELECTRONICS POWER MODULE - LH	Shorted	714.00 FS	*571.20 FS
19	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	524.00 FS	*- FS
20	1		*LED WITH HEAT SINK - LH	Not Necessary	689.00 FS	*- FS
21	1		*HEADLIGHT HOSE - LH	Not Necessary	38.00 FS	*- FS
22	1		*LIFT CYLINDER - LH	Not Necessary	134.00 FS	*- FS
23	1		*SUNDRIES	Necessary	300.00 FS	*15.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **12,943.00** **6,925.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT-PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			5,194.00	3,094.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >