

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CC3/MSG20004573/ESF3E2

Date: 29/04/2020

REFERENCE

Insured/Claimant: PHYLLIS CHENG SOK LENG
Date of Loss: 25/03/2020

Policy No: 29121145AVW
Nature of Claim: OD

Claim No: 622444

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB2525X	Engine No:	CZCC01204
Make & Model:	VOLKSWAGEN GOLF, 1.4 (A)	Chassis No:	WVWZZZAUZKW083297
Reg. Date:	28/03/2019 (Man. Year: 2018)	Odometer:	7427 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,023.01	10,018.85	3,004.16	23.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,415.00	7,990.00	5,425.00	40.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,438.01	18,008.85	8,429.16	31.88
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	25,938.01	17,508.85	8,429.16	32.50
+ GST 7.00/7.00% (S\$)	1,815.66	1,225.62	590.04	32.50
Nett Amount (S\$)	27,753.67	18,734.47	9,019.20	32.50

INSPECTION

Date of Assignment: 27/03/2020

Date Inspected: 27/03/2020 Inspected At:

Volkswagen Centre Singapore (Tuas)
17 TUAS AVENUE
Singapore 639176

Estimated Period of Repair: 11.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2020)
Parts:	144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGB2525X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Broken	1,033.46 FS	*1,033.46 FS
2	1		*RETAINER FOR SPOILER SATI	Crushed	165.22 FS	*165.22 FS
3	1		*GUIDE PIECE BUMPER BRACKET LHF	Not Necessary	18.34 FS	*- FS
4	1		*GUIDE PIECE BUMPER BRACKET RHF	Broken	18.34 FS	*18.34 FS
5	1		*SUPPORT PART BUMPER INNER BRACKET RHF	Broken	47.96 FS	*47.96 FS
6	1		*SENSOR BRACKET	Necessary	11.34 FS	*11.34 FS
7	2		*SENSOR BRACKET	Necessary	21.42 FS	*21.42 FS
8	1		*SENSOR BRACKET	Necessary	11.34 FS	*11.34 FS
9	1		*2K-PLASTIC ADHESIVE	Necessary	68.35 FS	*68.35 FS
10	1		*BONDING AGENT FOR PLASTIC	Necessary	53.46 FS	*53.46 FS
11	1		*RADIATOR GRILLE SATIN BLA	Not Necessary	399.54 FS	*- FS
12	1		*COOLING AIR GRILL SATIN B RHF FOG LAMP UPPER TRIM	Not Necessary	86.23 FS	*- FS
13	1		*GUIDE CENTRE BRACKET	Not Necessary	34.79 FS	*- FS
14	1		*LED HEADLIGHT RHF HEADLAMP	Not Necessary	2,397.26 FS	*- FS
15	1		*FENDER RHF FENDER	Dented	530.91 FS	*530.91 FS
16	1		*RIVETTED CAP NUT FENDER NUT (4PCS)	Necessary	4.10 FS	*4.10 FS
17	1		*CROSS SUPPORT FENDER BRACKET	Necessary	27.76 FS	*27.76 FS
18	1		*WHEELHOUSE LINER FENDER LINER TOP	Crushed	148.28 FS	*148.28 FS
19	1		*WHEELHOUSE LINER FENDER LINER BOTTOM	Crushed	76.47 FS	*76.47 FS
20	1		*SOUND ABSORBER FOR FENDER CLOSING ELEMENT	Torn	41.57 FS	*41.57 FS
21	1		*SOUND ABSORBER FOR FENDER FENDER TOP SPONGE	Necessary	13.15 FS	*13.15 FS
22	1		*DOOR RHF DOOR	Dented	1,788.44 FS	*1,788.44 FS
23	1		*DOOR SEAL	Necessary	90.61 FS	*90.61 FS
24	1		*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	37.26 FS	*37.26 FS
25	1		*SECTIONAL PART-PILLAR A/B A PILAR RHF	Dented	841.38 FS	*841.38 FS
26	1		*2K-INSERT FOAM	Necessary	130.45 FS	*130.45 FS
27	1		*SEALANT CAN BE SPRAYED	Necessary	55.50 FS	*55.50 FS
28	1		*ZINC SPRAY	Necessary	56.59 FS	*56.59 FS
29	1		*2K-BODY ADHESIVE	Necessary	366.08 FS	*366.08 FS
30	1		*LONG-LIFE UNDERSEAL	Necessary	72.86 FS	*72.86 FS
31	1		*WHEEL DISC ALUM. WITH	Cut	1,591.20 FS	*1,591.20 FS
32	1		*RUBBER VALVE	Necessary	2.96 FS	*2.96 FS
33	1		*QUERLENKER KOMPLETT LOWER ARM	Bent	303.40 FS	*303.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*GUIDE JOINT BALL JOINT	Necessary	112.57 FS	*112.57 FS
35	1		*WHEEL BEARING WITH MOUNTI	Necessary	548.46 FS	*548.46 FS
36	1		*RADLAGERGEHAUSE WHEEL BEARING HOUSING	Necessary	525.46 FS	*525.46 FS
37	1		*GAS-FILLED SHOCK ABSORBER	Bent	290.89 FS	*290.89 FS
38	1		*BALL BEARING TOP BEARING	Necessary	41.14 FS	*41.14 FS
39	1		*SUSPENSION STRUT MOUNTING TOP MOUNTING	Necessary	84.25 FS	*84.25 FS
40	1		*TIE ROD	Bent	92.21 FS	*92.21 FS
41	1		*TIE ROD END	Bent	126.86 FS	*126.86 FS
42	1		*RETAINING CLIP (2PCS)	Necessary	8.75 FS	*8.75 FS
43	1		*DEGREASER CLEANER 500ML	Necessary	34.40 FS	*34.40 FS
44	1		*PIRELLI CINTUP7 225/45R7 (\$680.00) (80%)	Torn	612.00 FS	*544.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **13,023.01** **10,018.85**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	R&R UNDERCARRIAGE	New	1,950.00	975.00
4	R&R RIM & BALANCING	New	50.00	50.00
5	TOWING FEE	New	195.00	195.00
6	LABOUR	New	5,200.00	2,600.00
7	SPRAY PAINTING	New	3,600.00	2,400.00
8	TRANSFER DOOR PARTS	New	650.00	325.00
9	R&R FRONT INNER LUGGAGE	New	650.00	325.00
10	WHEEL ALIGNMENT FOR MECHANICAL REPAIR UNDER OWN TECHNICIANS	New	360.00	360.00
Gross Labour Cost (\$\$)			13,415.00	7,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >