



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2100845

INV Date 08/02/2021

Reference CC6/LPC20004578/Uga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGS 5116J
Insured Veh. YL 4122X
Claim No. 19/20/20/VC05/023258
Policy No. Z19VC05004130
Accident Date 26/03/2020
Inspection Date 27/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC6/LPC20004578/Uga3q2 Date: 08/02/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 4122X	Veh. Inspected	SGS 5116J	
Policy No.	Z19VC05004130	Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023258	Excess (\$)	0.00	
Assign From		Assign Date	27/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ZNE100352465	Colour	BLACK	
Odometer	498955 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FIRENZA	6 mm	
L/H Front Tyre	205/55 R16	FIRENZA	6 mm	
R/H Rear Tyre	205/55 R16	FIRENZA	6 mm	
L/H Rear Tyre	205/55 R16	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/03/2020	Inspection Date	27/03/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 5116J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN	SHATTERED	1,288.50	1,215.10
1	REAR WINDSCREEN MOULDING	NECESSARY	128.70	128.70
1	TAILGATE	BADLY DENTED	1,866.10	1,248.10
1	TAILGATE INNER LOCK	DENTED / JAMMED	388.80	388.80
1	TAILGATE REAR LOGO	NECESSARY	68.10	68.10
1	TAILGATE "WISH" EMNLEM	NOT FITTED	60.50	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	645.10	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	299.50	299.50
1	TAILGATE OUTER CHROME MOULDING	BENT / CRACKED	388.20	388.20
2	TAILGATE DAMPERS @\$350.00	NOT NECESSARY	700.00	-
1	TAILGATE INNER HOLDER GARNISH	NOT NECESSARY	45.00	-
1	REAR BUMPER	DISTORTED	665.30	492.30
2	REAR BUMPER REFLECTORS @\$105.00	NOT NECESSARY	210.00	-
2	REAR BUMPER SIDE HOLDERS @\$68.50	NOT NECESSARY	137.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER DAMPERS @\$55.60	N/S BENT	111.20	55.60
1	REAR END PANEL	BADLY DENTED	699.10	699.10
1	REAR END PANEL LOWER MEMBER	BADLY DENTED	211.50	211.50
1	REAR END PANEL TOP GARNISH	TWISTED	288.60	288.60
2	TAILLAMPS @\$458.10	N/S BROKEN	916.20	408.10
2	TAILLAMP HOUSING PANELS @\$455.10	TO REPAIR SEE LABOUR	910.20	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,120.10	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	588.20	-
2	REAR FENDERS @\$977.10	TO REPAIR SEE LABOUR	1,954.20	-
2	REAR FENDER INNER TRIM BOARDS @\$605.10	N/S TORN	1,210.20	605.10
1	SET REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR EXHAUST	NOT NECESSARY	788.50	-
2	REAR EXHAUST MOUNTINGS @\$65.00	NOT NECESSARY	130.00	-

Report Ref No. CC6/LPC20004578/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	211.10	-
1	REAR SPARE TYRE BRACKET & CARRIAGE	NOT NECESSARY	450.50	-
1	REAR AIR VENT	NOT NECESSARY	121.00	-
1	BONNET	BUCKLED	678.10	678.10
1	BONNET INSULATOR	TORN	211.50	211.50
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
1	BONNET LOCK	BENT	145.50	145.50
1	BONNET OUTER CHROME MOULDING	CRACKED	155.30	155.30
2	HEADLAMPS @\$689.10	CRACKED	1,378.20	1,378.20
1	FRONT BUMPER	DISTORTED	830.00	645.10
1	FRONT BUMPER REINFORCEMENT	DISTORTED	266.20	266.20
1	FRONT BUMPER SPONGE	TORN	166.50	166.50
2	FRONT BUMPER SIDE HOLDERS @\$65.50	BENT	131.00	131.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT BUMPER FOG LAMP COVERS @\$68.00	NOT NECESSARY	136.00	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	188.20	-
1	FRONT GRILLE	TWISTED	166.60	166.60
1	FRONT BRACE PANEL	TWISTED	121.50	121.50
1	FRONT SUPPORT PANEL	BENT	688.10	688.10
1	AIR CON CONDENSER	BENT / PUNCTURE	1,213.10	1,213.10
1	AIR CON SUCTION HOSE	NOT NECESSARY	395.50	-
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	388.10	-
1	RADIATOR	BENT / PUNCTURE	1,866.50	1,866.50
1	RADIATOR FAN MOTOR	NOT NECESSARY	450.50	-
1	RADIATOR FAN BLADE	NOT NECESSARY	150.40	-
1	RADIATOR FAN COWLING	CRACKED	209.10	209.10
2	HORN UNITS @\$105.00	NOT NECESSARY	210.00	-
2	FRONT FENDERS @\$650.10	O/S BUCKLED / N/S TO REPAIR SEE LABOUR	1,300.20	650.10
2	FRONT FENDER INNERSHIELDS @\$195.10	NOT NECESSARY	390.20	-
	LESS 25% DISCOUNT		-	-3,834.80
			28,687.70	11,504.40

Report Ref No. CC6/LPC20004578/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR LICENCE PLATE W/HOLDER (SN)	SERVICEABLE	50.00	-
1	SET FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			730.00	310.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO REFILL AIRCON GAS.		150.00	100.00
	TO SPRAY RUST PROOFING.		200.00	120.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS,REAR FLOOR PANEL,REAR FENDERS AND N/S FRONT FENDER.		2,800.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,800.00
			6,790.00	3,560.00
GRAND TOTAL			36,207.70	15,374.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00
---	--	--	-----------------

Report Ref No. CC6/LPC20004578/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGS 5116J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGS 5116J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGS 5116J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

