

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004582/KEA3Q2

Date: 11/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472913

Claimant
Vehicle No : SLJ684G **Insured Vehicle No :** SLD7327Z

Date of Loss: 25/03/2020 Nature of Claim: TP Claim No: 0260218746SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ684G		
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Engine No:	1NZR431715
Reg. Date:	28/11/2016 (Man. Year: 2016)	Chassis No:	NHP1707056492
Colour:	Metallic Blue	Odometer:	56269 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,915.48	2,604.38	311.10	10.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,430.00	150.00	9.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,495.48	4,034.38	461.10	10.26
+ GST 7.00/7.00% (S\$)	314.68	282.41	32.27	10.25
Nett Amount (S\$)	4,810.16	4,316.79	493.37	10.26
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,744.79		

INSPECTION

Date of Assignment: 26/03/2020

Date Inspected: 27/03/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
10 ANG MO KIO IND PARK 2A, #01-
04 ANG MO KIO AUTOPOINT
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	278.00 FL	*278.00 FL
2	1		*REAR BUMPER SPONGE	Not Necessary	25.60 FL	*- FL
3	1		*REAR BUMPER CENTRE PAD	Dented	180.70 FL	*180.70 FL
4	1		*REAR BUMPER LH SIDE PAD	Dented	122.80 FL	*122.80 FL
5	1		*REAR BUMPER LH SIDE REFLECTOR	Cracked	56.90 FL	*56.90 FL
6	1		*REAR BUMPER LH SIDE RETAINER	Distorted	92.33 FL	*92.33 FL
7	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
8	1		*REAR TAILGATE	Bent	1,076.00 FL	*1,076.00 FL
9	1		*TAILGATE INNER LOCK	Not Necessary	389.20 FL	*- FL
10	1		*TAILGATE INNER RUBBER	Cut	325.70 FL	*325.70 FL
11	1		*TAILGATE LOGO	Necessary	75.25 FL	*75.25 FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	82.90 FL	*82.90 FL
13	1		*TAILGATE LH REFLECTOR	Cut	104.00 FL	*104.00 FL
14	1		*LH TAILLAMP	Cut	327.00 FL	*327.00 FL
15	1		*REAR END PANEL	Dented	374.00 FL	*374.00 FL
16	1		*REAR END PANEL INNER TOP GARNISH	Mtg Distorted	232.00 FL	*232.00 FL
17	1		*TAILGATE EMBLEM (HYBRID)	Necessary	63.60 FL	*63.60 FL
18	1		*TAILGATE WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,873.98	3,459.18
- List Item Discount on L Items 25.00/25.00% (\$\$)	958.50	854.80
Total Parts (\$\$)	2,915.48	2,604.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS TAILGATE & ATTACHMENTS ,CUT ,WELD & RENEW REAR END PANEL ,KNOCK & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	New	750.00	600.00
3	PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,REAR END PANEL ,REAR LH FENDER & ALL AFFECTED AREAS	New	600.00	600.00
4	REMOVE & REFIX REVERSE CAMERA ,RESET & REALIGN THE SAME	New	50.00	50.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,580.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >