

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004583/AGA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100485086

Claimant
Vehicle No : SJQ79R **Insured Vehicle No :** GBF3783Z

Date of Loss: 24/03/2020 Nature of Claim: TP Claim No: 6257515569SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ79R		
Make & Model:	LEXUS GS350, 3.5 (A)	Engine No:	2GR8738149
Reg. Date:	02/04/2012 (Man. Year: 2012)	Chassis No:	JTHBE1BL605002702
Colour:	Brown	Odometer:	165564 km
Engine Capacity:	3456 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,778.99	6,322.16	1,456.83	18.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	630.00	1,190.00	65.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,598.99	6,952.16	2,646.83	27.57
Approved Total (Overridden) (\$\$)		5,500.00		
(\$\$)	9,598.99	5,500.00	4,098.99	42.70
+ GST 7.00/7.00% (\$\$)	671.93	385.00	286.93	42.70
Nett Amount (\$\$)	10,270.92	5,885.00	4,385.92	42.70
+ Car Rental (3.0 x S\$150.00/day) (\$\$)		450.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,342.45		
Global Sum Settlement (\$\$)		6,300.00		

INSPECTION

Date of Assignment: 25/03/2020

Date Inspected: 25/03/2020 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	920.00 FL	*920.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	138.72 FL	*138.72 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	680.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	230.00 FL	*230.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Cracked	210.00 FL	*210.00 FL
6	1		*FRONT BUMPER REVERSE SENSOR	Damaged	320.00 FL	*240.00 FL
7	1		*FRONT BUMPER INNER AIR DUCT	Not Necessary	290.00 FL	*- FL
8	1		*FRONT BUMPER NUMBER PLATE HOLDER	Deformed	190.00 FL	*190.00 FL
9	1		*CENTRE GRILLE	Cut	988.70 FL	*878.00 FL
10	1		*CENTRE GRILLE CHROME	Cut	360.00 FL	*360.00 FL
11	1		*CENTRE GRILLE LOGO	Necessary	190.00 FL	*190.00 FL
12	1		*HEADLAMP RH	Cracked	3,885.90 FL	*3,567.90 FL
13	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	140.00 FL	*- FL
14	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
15	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
16	1		*SET CENTRE GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,633.32	7,014.62
- List Item Discount on L Items 10.00/10.00% (\$\$)	854.33	692.46
Total Parts (\$\$)	7,778.99	6,322.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	600.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	600.00	250.00
3	TUFF COAT	New	180.00	0.00
4	WIRING CHECK	New	100.00	30.00
5	TO REMOVE AND REFIX FRONT REVERSE SENSOR	New	120.00	50.00
6	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	220.00	0.00
Gross Labour Cost (\$\$)			1,820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >