

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004586/ASF3E2
Date: 19/01/2021

REFERENCE

Insured/Claimant: RORO DEWI MASHITA BINTI MAMAT Policy No: 2100473271-03
Date of Loss: 24/03/2020 Nature of Claim: OD Claim No: 8531663598SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD8595J**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (180BHP) (A) Engine No: CNC168468
Reg. Date: 29/06/2016 (Man. Year: 2016) Chassis No: WAUZZZ8R5GA141796
Colour: Brown Odometer: 62692 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,586.00	7,457.60	6,128.40	45.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,312.00	7,162.00	8,150.00	53.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,898.00	14,619.60	14,278.40	49.41
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	27,898.00	13,619.60	14,278.40	51.18
+ GST 7.00/7.00% (S\$)	1,952.86	953.37	999.49	51.18
Nett Amount (S\$)	29,850.86	14,572.97	15,277.89	51.18

INSPECTION

Date of Assignment: 27/03/2020
Date Inspected: 27/03/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	2,972.00 FS	*2,377.60 FS
2	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
3	1		*FRONT DOOR OUTER SEAL - LH	Necessary	193.00 FS	*154.40 FS
4	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
5	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
6	1		*FRONT DOOR CATCH	Not Necessary	137.00 FS	*- FS
7	1		*FRONT DOOR COVER - LH	Deformed	482.00 FS	*385.20 FS
8	1		*REAR DOOR - LH	Distorted	2,972.00 FS	*2,377.60 FS
9	1		*REAR DOOR OUTER SEAL - LH	Necessary	193.00 FS	*154.40 FS
10	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
11	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
12	1		*STONE CHIP PROTECTION FILM - LH INNER	Necessary	73.00 FS	*58.40 FS
13	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	117.00 FS	*- FS
14	1		*REAR DOOR CATCH	Not Necessary	137.00 FS	*- FS
15	2		*REAR DOOR HINGE - LH UPPER / LOWER	Not Necessary	285.00 FS	*- FS
16	1		*SILL PANEL SEAL - LH	Necessary	209.00 FS	*167.20 FS
17	1		*INNER DOOR SEAL	Not Necessary	193.00 FS	*- FS
18	1		*REAR DOOR COVER - LH	Missing	385.00 FS	*308.00 FS
19	1		*SILL PANEL - LH	Repair	2,031.00 FS	*- FS
20	1		*SILL TRIM STRIP - LH REAR	Necessary	135.00 FS	*108.00 FS
21	1		*REAR ALUMINIUM RIM - LH	Cut	944.00 FS	*754.80 FS
22	1		*UNDERBODY TRIM - LH	Deformed	315.00 FS	*252.00 FS
23	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	248.00 FS	*- FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	98.00 FS	*- FS
25	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
26	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
27	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
28	1		*SUNDRIES	Necessary	400.00 FS	*3.36 FS
29	1		*SILL TRIM STRIP FOR FRONT DOOR ENTRANCES LHS	Necessary	226.00 FS	*180.80 FS
Total Parts (S\$)					13,586.00	7,457.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	560.00	560.00
2	TO REMOVE AND REINSTALL LHS REAR BACK REST, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,400.00	0.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	1,500.00
4	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR COVERS, LHS SILL PANEL AND DOOR ENTRANCES. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,600.00	2,050.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND REINSTALL LHS B-PILLAR LOWER TRIM TO FACILITATE B-PILLAR REPAIR. INCLUSIVE OF SEAT BELT	New	480.00	480.00
8	TO REPAIR LHS SILL PANEL AND LHS B-PILLAR	New	1,000.00	1,000.00
9	TO RESPRAY LHS SILL PANEL AND LHS B-PILLAR	New	2,000.00	1,100.00
Gross Labour Cost (\$\$)			15,312.00	7,162.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >