

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20004587/BVF3E2
Date: 17/06/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001890
Claimant Vehicle No : SHD6899T	Insured Vehicle No :	YM6532C
Date of Loss: 25/03/2020	Nature of Claim:	TP Claim No: M2002128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6899T		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFDU504530
Reg. Date:	08/10/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU078429
Colour:	Blue	Odometer:	623897 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,029.36	10,495.24	10,534.12	50.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,770.00	1,710.00	49.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,509.36	12,265.24	12,244.12	49.96
Approved Total (Overridden) (S\$)		9,800.00		
(S\$)	24,509.36	9,800.00	14,709.36	60.02
+ GST 7.00/7.00% (S\$)	1,715.66	686.00	1,029.66	60.02
Nett Amount (S\$)	26,225.02	10,486.00	15,739.02	60.02

INSPECTION

Date of Assignment:	27/03/2020	
Date Inspected:	27/03/2020 Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2020)
Parts: 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6899T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID	Bent / Dented	2,174.90 FL	-	*2,174.90 FL
2	1		*BOOTLID RUBBER	Deformed	96.50 FL	-	*96.50 FL
3	2		*BOOTLID HINGE (LH/RH)	Not Necessary	569.20 FL	-	*- FL
4	1		*BOOTLID LOCK UPPER	Bent	114.90 FL	-	*114.90 FL
5	1		*BOOTLID LOCK LOWER	Bent	23.20 FL	-	*23.20 FL
6	1		*BOOTLID I40 EMBLEM (I40)	Serviceable	67.90 FL	-	*- FL
7	1		*BOOTLID H EMBLEM	Necessary	63.10 FL	-	*63.10 FL
8	1		*BOOTLID CRDI PLATE	Necessary	52.40 FL	-	*52.40 FL
9	1		*BOOTLID LAMP (LH/RH) (2PCS)	Mtg Cracked (1Pc Only)	2,262.40 FL	-	*1,131.20 FL
10	1		*BOOTLID TRIMBOARD	Serviceable	343.90 FL	-	*- FL
11	11		*BOOTLID TRIMBOARD CLIPS	Not Necessary	11.00 FL	-	*- FL
12	1		*BOOTLID MOULDING (I40)	Serviceable	385.30 FL	-	*- FL
13	1		*BOOTLID LOWER GARNISH CHROME (I40)	Serviceable	227.90 FL	-	*- FL
14	1		*REAR BUMPER	Dented	1,106.00 FL	-	*553.00 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	160.60 FL	-	*160.60 FL
16	1		*REAR BUMPER REINFORCEMENT	Broken	428.40 FL	-	*428.40 FL
17	1		*REAR BUMPER CLIP	Necessary	19.00 FL	-	*19.00 FL
18	1		*REAR BUMPER SPONGE	Torn	119.50 FL	-	*119.50 FL
19	1		*REAR BUMPER UNDER COVER	Deformed	228.00 FL	-	*228.00 FL
20	1		*REAR BUMPER RUBBER MAT / I40 PLATE	Necessary	50.00 FS	-	*50.00 FS
21	2		*REAR BUMPER REFLECTOR LAMP (I40)	Not Necessary	64.00 FL	-	*- FL
22	2		*TAIL LAMP (LH/RH)	Mtg Cracked	1,395.60 FL	-	*1,395.60 FL
23	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	906.00 FL	-	*- FL
24	1		*REAR PANEL	Buckled	526.70 FL	-	*526.70 FL
25	1		*REAR PANEL LOWER	Buckled	367.20 FL	-	*367.20 FL
26	1		*REAR PANEL GARNISH	Bent / Mtg Deformed	57.70 FL	-	*57.70 FL
27	2		*PANEL ASSY-REAR FLOOR SIDE (LH/RH)	Not Necessary	354.00 FL	-	*- FL
28	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	-	*- FL
29	1		*SPARE WHEEL LOCK NUT	Bent / Broken	41.80 FL	-	*41.80 FL
30	1		*SPARE TYRE PANEL	Dented	852.80 FL	-	*852.80 FL
31	1		*SPARE TYRE PANEL CUSHION	Not Necessary	223.10 FL	-	*- FL
32	1		*MEMBER-ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
33	1		*REAR TOWING HOOK	Not Necessary	194.60 FL	-	*- FL
34	1		*REAR FLOOR CHASSIS MEMBER (LH)	Not Necessary	4,232.50 FL	-	*- FL
35	2		*EXHAUST PIPE INSULATOR (LH/RH)	Not Necessary	234.20 FL	-	*- FL
36	2		*EXHAUST SILENCER (LH/RH)	Dented	3,870.80 FL	-	*1,935.40 FL
37	1		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	-	*- FL
38	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	-	*- FL
39	1		*BOOTLID ADVERTISEMENT LOGO	Necessary	100.00 FS	-	*100.00 FS
40	1		*REAR NO. PLATE	Not Necessary	25.00 FS	-	*- FS
41	1		*REAR BUMPER REVERSE SENSOR	Damaged	118.00 FS	-	*118.00 FS
42	1		*REAR BUMPER ADVERTISEMENT LOGO	Not fitted	50.00 FS	-	*- FS
43	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	-	*200.00 FS
44	1		*REAR FENDER	Dented	2,171.40 FL	-	*2,171.40 FL
45	1		*BOOTLID COMFORT LOGO & TEL NO. STICKER	Necessary	16.60 FS	-	*16.60 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	26,146.80	12,997.90
- List Item Discount on L Items 20.00/20.00% (\$)	5,117.44	2,502.66
Total Parts (\$)	21,029.36	10,495.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	800.00
2	WIRING CHARGE	New	80.00	30.00
3	TUFF KOTE	New	120.00	40.00
4	TOWING CHARGE	New	80.00	0.00
5	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
6	REMOVE / REFIX EXHAUST PIPE	New	80.00	60.00
7	SPRAY PAINTING CHARGE	New	1,400.00	800.00
Gross Labour Cost (\$\$)			3,480.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >