

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD20004588/UGA3Q2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00013994-01

**Claimant Vehicle No :** SJL9777B **Insured Vehicle No :** SKU2135R

Date of Loss: 26/03/2020 Nature of Claim: TP Claim No: 1202000015325

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJL9777B</b>		
Make & Model:	HONDA STREAM, 1.8 RSZ (A)	Engine No:	R18A1785116
Reg. Date:	29/10/2008 (Man. Year: 2008)	Chassis No:	RN61076726
Colour:	Grey	Odometer:	218390 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,779.00	3,911.92	6,867.08	63.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	2,340.00	2,960.00	55.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,079.00</b>	<b>6,251.92</b>	<b>9,827.08</b>	<b>61.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>(S\$)</b>	16,079.00	5,000.00	11,079.00	68.90
<b>+ GST 7.00/7.00% (S\$)</b>	1,125.53	350.00	775.53	68.90
<b>Nett Amount (S\$)</b>	<b>17,204.53</b>	<b>5,350.00</b>	<b>11,854.53</b>	<b>68.90</b>

### INSPECTION

Date of Assignment: 27/03/2020

Date Inspected: 27/03/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2020)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJL9777B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	48.50 F	*48.50 FL
2	1	*TAILGATE	Badly Dented	903.20 F	*903.20 FL
3	1	*TAILGATE H LOGO	Not Necessary	35.20 F	*- FL
4	1	*TAILGATE STREAM EMBLEM	Necessary	32.60 F	*32.60 FL
5	1	*TAILGATE RSZ EMBLEM	Necessary	38.80 F	*38.80 FL
6	1	*TAILGATE OUTER GARNISH	Not Necessary	184.50 F	*- FL
7	1	*TAILGATE INNER LOCK	Dented / Shorted	109.50 F	*109.50 FL
8	1	*TAILGATE INNER TRIM BOARD	Not Necessary	341.50 F	*- FL
9	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
10	1	*TAILGATE WEATHERSTRIP	Twisted	116.90 F	*116.90 FL
11	2	*TAILGATE DAMPERS	Not Necessary	490.20 F	*- FL
12	1	*REAR BUMPER	Distorted	665.40 F	*665.40 FL
13	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	51.00 F	*- FL
14	1	*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
15	1	*REAR END PANEL	Badly Dented	306.10 F	*306.10 FL
16	1	*REAR END PANEL LOWER MEMBER	Badly Dented	182.30 F	*182.30 FL
17	1	*REAR END PANEL TOP GARNISH	Twisted	225.60 F	*225.60 FL
18	1	*REAR FLOOR PANEL	Repair	912.30 F	*- FL
19	2	*REAR FLOOR PANEL TOP BOARDS	Not Necessary	533.00 F	*- FL
20	2	*REAR TAILLAMPS	Cracked	1,782.20 F	*733.00 FL
21	2	*REAR FENDER INNER TRIM BOARDS	Deformed / Cracked	790.40 F	*790.40 FL
22	1	*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
23	1	*REAR EXHAUST	Repair	689.30 F	*- FL
24	2	*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
25	1	*REAR SPARE TYRE BRACKET	Bent	285.10 F	*285.10 FL
26	2	*REAR BUMPER LOWER BRACKETS	Bent	51.00 F	*51.00 FL
27	1	*CENTRE EXHAUST PIPE	Not Necessary	685.40 F	*- FL
28	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
29	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
30	1	*REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS
31	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1	*REAR QUARTER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
33	1	*SET REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,779.00</b>	<b>4,817.40</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>905.48</b>
<b>Total Parts (\$\$)</b>	<b>10,779.00</b>	<b>3,911.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REVERSE CAMERA	New	80.00	0.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO TRANSFER TAILGATE COMPONENTS	New	100.00	60.00
6	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
7	TO DISMANTLE & REPLACING REAR EXHAUST	New	180.00	60.00
8	TO SPRAY RUST PROOFING	New	150.00	60.00
9	TO MOUNT VEHICLE ON JIG BENCE	New	380.00	0.00
10	TO SPRAY RUST PROOFING	New	150.00	0.00
11	LABOUR FOR PANEL BEATING ,CUT ,WELD & STRAIGHTEN & REPLACING PARTS	New	1,800.00	880.00
12	TO PUTY & SPRAY PAINTING	New	2,000.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,300.00</b>	<b>2,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >