



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2005638
INV Date 17/08/2020
Reference CC4/EQI20004590/Ega3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. VCR 8480
Insured Veh. SGS 8241K
Claim No. DM20HO00634/SG
Policy No. DMCFHQ19-000090
Accident Date 23/03/2020
Inspection Date 27/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20004590/Ega3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 17-08-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 8241K	Veh. Inspected	VCR 8480
Policy No.	DMCFHQ19-000090	Coverage (\$)	0.00
Claim No.	DM20HO00634/SG	Excess (\$)	0.00
Assign From	JANICE	Assign Date	27/03/2020

2. Vehicle Particulars & Condition

Make & Model	KAWASAKI VERSYS	c.c	649
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JKALE650CCDA14787	Colour	YELLOW
Odometer	16005	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70Z R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/70Z R17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/03/2020	Inspection Date	27/03/2020
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. VCR 8480

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FORK RH	BENT	880.00	880.00
1	FRONT MUDGUARD	BROKEN	385.00	385.00
1	FRONT BRAKE DISC RH	CUT	950.00	600.00
1	SPORT LIGHT	BROKEN	320.00	320.00
1	FRONT SPORT RIM	CUT / BENT	1,350.00	1,200.00
1	FRONT BRAKE PLATE CALIPER	NOT NECESSARY	680.00	-
1	CENTRE FAIRING CAP	CUT	166.00	166.00
1	RADIATOR	DENTED	845.00	845.00
1	WATER PIPE	CRUSHED	45.00	45.00
1	LOWER COWLING	BROKEN	350.00	350.00
1	HORN	BROKEN	75.00	75.00
1	MIRROR	CUT	260.00	130.00
1	HANDLE BAR	BENT	240.00	240.00
1	HAND GUARD	CUT	340.00	170.00
1	WINDSCREEN	CUT	320.00	320.00
1	CENTRE FAIRING LH	BROKEN	560.00	560.00
1	FUEL TANK SIDE PLATE	NOT NECESSARY	290.00	-
1	BODY OLIDER	BENT	160.00	160.00
1	FOOTREST BRACKET	BROKEN	220.00	220.00
1	FRONT FOOTREST	BROKEN	85.00	85.00
1	GEAR LEVER	CUT	160.00	160.00
1	FRONT FAIRING	CUT	430.00	430.00
1	MAGNETO COVER	CUT	390.00	390.00
1	GIVI E450 BOX	CUT	180.00	180.00
	LESS 10% DISCOUNT		-968.10	-791.10
			8,712.90	7,119.90
	<u>SPECIAL NETT ITEMS</u>			
1	GASKET (SN)	NECESSARY	25.00	25.00
			25.00	25.00

Report Ref No. CC4/EQI20004590/Ega3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TRANSPORT .		40.00	40.00
	ENGINE OIL .		60.00	30.00
	COOLANT.		35.00	20.00
	LABOR .		450.00	350.00
			585.00	440.00
	GRAND TOTAL		9,322.90	7,584.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,050.00

Report Ref No. CC4/EQI20004590/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R

PHOTOGRAPHS FOR VEHICLE NO. VCR 8480

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R

PHOTOGRAPHS FOR VEHICLE NO. VCR 8480

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Pava Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9507198-R

