

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20004592/UGA3Q2

**Date:** 08/04/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800068701  
**Claimant**  
**Vehicle No :** FBD8706A **Insured Vehicle No :** SMA6685A  
Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: 1673726210SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBD8706A**  
Make & Model: HONDA WAVE 125, 125cc Engine No: NF125STE0027943  
Reg. Date: 07/09/2009 (Man. Year: 2009) Chassis No: NF125ST0027943  
Colour: Blue Odometer: 50609 km  
Engine Capacity: 125 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 80-90-17 Rear Tyre Size: 80-90-17  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,030.00	2,466.20	1,563.80	38.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	938.00	385.00	553.00	58.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,968.00</b>	<b>2,851.20</b>	<b>2,116.80</b>	<b>42.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>(S\$)</b>	4,968.00	2,250.00	2,718.00	54.71
<b>+ GST 7.00/7.00% (S\$)</b>	347.76	157.50	190.26	54.71
<b>Nett Amount (S\$)</b>	<b>5,315.76</b>	<b>2,407.50</b>	<b>2,908.26</b>	<b>54.71</b>
<b>+ Loss of Use (5.0 x S\$20.00/day) (S\$)</b>		100.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,509.50</b>		

#### INSPECTION

Date of Assignment: 27/03/2020  
Date Inspected: 27/03/2020 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)  
No. 6 Defu Lane 4  
Singapore 539410  
Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY	Not Necessary	490.00 F	*- FL
2	1		*BAR HANDLE	Bent	54.00 F	*54.00 FL
3	1		*BASE COMP	Cracked	27.00 F	*27.00 FL
4	1		*BASE COMP (TOP)	Cracked	27.00 F	*27.00 FL
5	1		*BASKET FRONT	Bent	33.00 F	*33.00 FL
6	1		*BEARING (6301UU)	Necessary	20.00 F	*20.00 FL
7	2		*BEARING RADIAL BALL (620IU)	Necessary	40.00 F	*40.00 FL
8	1		*BEARING RADIAL BALL (6201UU)	Necessary	14.00 F	*14.00 FL
9	1		*BOX AIR CLEANER	Cracked	33.00 F	*33.00 FL
10	1		*BRACKET UNDER FORK	Bent	192.00 F	*192.00 FL
11	2		*STOCK AVAILABILITY (DAYS)1	Not Necessary	14.00 F	*- FL
12	1		*CABLE COMP CHOKE	Twisted	16.00 F	*16.00 FL
13	2		*CAP LOCK NUT	Not Necessary	20.00 F	*- FL
14	1		*CARBURETOR ASSY	Torn	266.00 F	*266.00 FL
15	4		*COLLAR MAIN STEP	Not Necessary	40.00 F	*- FL
16	1		*COVER AIR CLEANER BOX	Cut	33.00 F	*33.00 FL
17	1		*COVE LEG SHIELD	Deformed	60.00 F	*60.00 FL
18	1		*COVER LEG SHIELD	Cracked	26.00 F	*26.00 FL
19	1		*COVER LEG SHIELD	Cracked	60.00 F	*60.00 FL
20	1		*COVER RR HANDLE	Cracked	26.00 F	*26.00 FL
21	1		*COVER SET ,FR	Cracked	54.00 F	*54.00 FL
22	1		*COVER SET,HANDLE	Cracked	61.00 F	*61.00 FL
23	1		*COVER SET ,L.MAIN PIPE SIDE	Cracked	82.00 F	*82.00 FL
24	1		*COVER SET ,LH	Cracked	60.00 F	*60.00 FL
25	1		*COVER ,L CYLINDER HEAD SIDE	Cracked	33.00 F	*33.00 FL
26	1		*DUST SEAL 40X50X5	Necessary	10.00 F	*10.00 FL
27	1		*FENDER FORK FRONT	Cut	40.00 F	*40.00 FL
28	1		*FOOREST FRONT	Torn	30.00 F	*30.00 FL
29	1		*FORK LH ASSY	Dented	213.00 F	*213.00 FL
30	1		*FORK RH ASSY	Serviceable	213.00 F	*- FL
31	1		*GASKET AIR FEED PIPE	Necessary	12.00 F	*12.00 FL
32	1		*GASKET CYLINDER HEAD COVER	Not Necessary	10.00 F	*- FL
33	1		*GASKET EXHAUST PIPE (MIDDLE)	Not Necessary	11.00 F	*- FL
34	1		*HELMET (TRAX) TR03-ZR BLACK -M	Serviceable	85.00 F	*- FL
35	1		*INSULATOR CARBURETOR	Necessary	12.00 F	*12.00 FL
36	1		*LENS SIGNAL FRONT LH	Cracked	19.00 F	*19.00 FL
37	1		*LEVER BRAKE RH	Bent	16.00 F	*16.00 FL
38	1		*MIRROR LH	Broken	22.00 F	*22.00 FL
39	1		*MIRROR RH	Broken	22.00 F	*22.00 FL
40	1		*MUDGUARD REAR	Distorted	40.00 F	*40.00 FL
41	1		*MUFFLER COMP	Repair	171.00 F	*- FL
42	2		*NUT LOCK	Necessary	20.00 F	*20.00 FL
43	1		*O-RING (40.5X3)	Not Necessary	10.00 F	*- FL
44	1		*O-RING (25X2.4)	Not Necessary	5.00 F	*- FL
45	2		*O-RING 16.5X2.5		24.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*PEDAL COMP ,BRAKE	Not Necessary Repair	28.00 F	*- FL
47	1		*PEDAL GEAR CHANGE	Bent	23.00 F	*23.00 FL
48	1		*PIN COLTER	Not Necessary	7.00 F	*- FL
49	1		*PIPE VACUUM	Serviceable	28.00 F	*- FL
50	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	27.00 FS	*10.00 FS
51	1		*RACE ,STEERING TOP BALL	Necessary	48.00 F	*48.00 FL
52	1		*RIM SPORT (FRONT) (RACING BOY)	Bent	280.00 F	*280.00 FL
53	4		*RUBBER FOOTREST FRONT STOPPER	Necessary	32.00 F	*32.00 FL
54	2		*RUBBER FOOTREST FRONT	Torn	16.00 F	*16.00 FL
55	1		*RUBBER HUB REAR	Torn	20.00 F	*20.00 FL
56	2		*SCREW	Not Necessary	20.00 F	*- FL
57	2		*SCREW	Not Necessary	20.00 F	*- FL
58	2		*SCREW -WASHER4*16	Not Necessary	10.00 F	*- FL
59	6		*SCREW ,TAPPING (4X12)	Not Necessary	30.00 F	*- FL
60	2		*SCREW ,TAPPING (4X16)	Not Necessary	10.00 F	*- FL
61	1		*SEAL OIL 21X37X7	Not Necessary	10.00 F	*- FL
62	1		*SHIELD SET ,L LED	Cracked	60.00 F	*60.00 FL
63	1		*SHIELD SET ,R LED	Cracked	60.00 F	*60.00 FL
64	1		*SIGNAL FRONT RH	Cracked	19.00 F	*19.00 FL
65	1		*STAY ,FR TOP COVER	Bent	33.00 F	*33.00 FL
66	1		*STEM SUB ASSY ,STEERING	Bent	192.00 F	*192.00 FL
67	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	19.00 FS	*10.00 FS
68	1		*SWITCH BRAKE FRONT	Damaged	16.00 F	*16.00 FL
69	1		*TUBE TIRE	Not Necessary	10.00 F	*- FL
70	1		*GRIP HANDLE (RCB)	Torn	49.00 F	*49.00 FL
71	1		*OIL FORK (ELF PERFO) XC 10W	Necessary	10.00 F	*10.00 FL
72	2		*SEAL OIL (26X37X10.5) FORK COMP	Necessary	41.00 F	*41.00 FL
73	2		*TUBE INNER FORK	Bent	146.00 F	*146.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,030.00</b>	<b>2,738.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	271.80
<b>Total Parts (\$\$)</b>	<b>4,030.00</b>	<b>2,466.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	882.00	350.00
2	TRANSPORT CHARGES	New	56.00	35.00
<b>Gross Labour Cost (S\$)</b>			<b>938.00</b>	<b>385.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >