

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2020 Edit Reg		27 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: TEMPUR SINGAPORE PTE LTD , Co. Reg. No.: 199003016K									
Main Claimant: TOH JUNLIANG KENT									
Vehicle Reg. No.: SJV2111R		Date of Loss: 26/03/2020 14:00 - :59 [145 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7817890920SG		Policy/Cover Note No.: 2100444699 (Comprehensive)							
Vehicle Reg. No. (Insured): GBE5233L		Policy No. (Claimant):							
		Excess:							
Repairer: Elites Performance (HQ) 51 DEFU LANE 9, 539291 Defu Lane - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 07/04/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV2111R (7817890920SG)**
[GBE5233L]
TP
TOH JUNLIANG KENT
Mar 26 2020 2:00PM
[TEMPUR SINGAPORE PTE LTD]
Elites Performance

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼		
Photos/Images			3 per page ▼	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/04/20 18:32	Chassis Number		Load JPG	☒
2	13/04/20 18:32	Odometer Reading		Load JPG	☒
3	13/04/20 18:32	General View		Load JPG	☒
4	13/04/20 18:32	General View		Load JPG	☒
5	13/04/20 18:32	General View		Load JPG	☒
6	13/04/20 18:32	General View		Load JPG	☒
7	13/04/20 18:32	General View		Load JPG	☒
8	13/04/20 18:32	General View		Load JPG	☒
9	13/04/20 18:32	General View		Load JPG	☒
10	13/04/20 18:32	General View		Load JPG	☒
11	13/04/20 18:32	General View		Load JPG	☒
12	13/04/20 18:32	General View		Load JPG	☒
13	13/04/20 18:32	General View		Load JPG	☒
14	13/04/20 18:32	General View		Load JPG	☒
15	13/04/20 18:32	General View		Load JPG	☒
16	13/04/20 18:32	General View		Load JPG	☒
17	13/04/20 18:32	General View		Load JPG	☒
18	13/04/20 18:32	General View		Load JPG	☒
19	13/04/20 18:32	General View		Load JPG	☒
20	13/04/20 18:32	General View		Load JPG	☒
21	13/04/20 18:32	General View		Load JPG	☒
22	13/04/20 18:32	General View		Load JPG	☒
23	13/04/20 18:32	General View		Load JPG	☒
24	13/04/20 18:32	General View		Load JPG	☒
25	13/04/20 18:32	General View		Load JPG	☒
26	13/04/20 18:32	General View		Load JPG	☒
27	13/04/20 18:32	General View		Load JPG	☒
28	13/04/20 18:32	General View		Load JPG	☒
29	13/04/20 18:32	General View		Load JPG	☒
30	13/04/20 18:32	General View		Load JPG	☒
31	13/04/20 18:32	General View		Load JPG	☒
32	13/04/20 18:32	General View		Load JPG	☒
33	13/04/20 18:32	General View		Load JPG	☒
34	13/04/20 18:32	General View		Load JPG	☒
35	13/04/20 18:32	General View		Load JPG	☒
36	13/04/20 18:32	General View		Load JPG	☒
37	13/04/20 18:34	After Repair Photo		Load JPG	☒
38	13/04/20 18:34	After Repair Photo		Load JPG	☒
39	13/04/20 18:34	After Repair Photo		Load JPG	☒
40	13/04/20 18:34	After Repair Photo		Load JPG	☒

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	13/04/20 18:34	After Repair Photo		Load JPG	☒
42	13/04/20 18:34	After Repair Photo		Load JPG	☒
43	13/04/20 18:34	After Repair Photo		Load JPG	☒
44	13/04/20 18:34	After Repair Photo		Load JPG	☒
45	13/04/20 18:34	After Repair Photo		Load JPG	☒
46	13/04/20 18:34	After Repair Photo		Load JPG	☒
47	13/04/20 18:34	After Repair Photo		Load JPG	☒
48	13/04/20 18:34	After Repair Photo		Load JPG	☒
49	13/04/20 18:34	After Repair Photo		Load JPG	☒
50	13/04/20 18:34	After Repair Photo		Load JPG	☒
51	13/04/20 18:34	After Repair Photo		Load JPG	☒
52	11/05/20 16:17	Dismantled Parts		Load JPG	☒
53	11/05/20 16:17	Dismantled Parts		Load JPG	☒
54	11/05/20 16:17	Dismantled Parts		Load JPG	☒
55	11/05/20 16:17	Dismantled Parts		Load JPG	☒
56	11/05/20 16:17	Dismantled Parts		Load JPG	☒
57	11/05/20 16:17	Dismantled Parts		Load JPG	☒
58	11/05/20 16:17	Dismantled Parts		Load JPG	☒
59	11/05/20 16:17	Dismantled Parts		Load JPG	☒
60	11/05/20 16:17	Dismantled Parts		Load JPG	☒
61	11/05/20 16:17	Dismantled Parts		Load JPG	☒
62	11/05/20 16:17	Dismantled Parts		Load JPG	☒
63	11/05/20 16:17	Dismantled Parts		Load JPG	☒
64	11/05/20 16:17	Dismantled Parts		Load JPG	☒
65	11/05/20 16:17	Dismantled Parts		Load JPG	☒
66	11/05/20 16:17	Dismantled Parts		Load JPG	☒
67	11/05/20 16:17	Dismantled Parts		Load JPG	☒
68	11/05/20 16:17	Dismantled Parts		Load JPG	☒
69	11/05/20 16:17	Dismantled Parts		Load JPG	☒
70	11/05/20 16:17	Dismantled Parts		Load JPG	☒
71	11/05/20 16:17	Dismantled Parts		Load JPG	☒
72	11/05/20 16:17	Dismantled Parts		Load JPG	☒
73	11/05/20 16:17	Dismantled Parts		Load JPG	☒
74	11/05/20 16:17	Dismantled Parts		Load JPG	☒
75	11/05/20 16:17	Dismantled Parts		Load JPG	☒
76	11/05/20 16:17	Dismantled Parts		Load JPG	☒
77	11/05/20 16:17	Dismantled Parts		Load JPG	☒
78	11/05/20 16:17	Dismantled Parts		Load JPG	☒
79	11/05/20 16:17	Dismantled Parts		Load JPG	☒
80	11/05/20 16:17	Dismantled Parts		Load JPG	☒
81	11/05/20 16:17	Dismantled Parts		Load JPG	☒
82	11/05/20 16:17	Dismantled Parts		Load JPG	☒
83	11/05/20 16:17	Dismantled Parts		Load JPG	☒
84	11/05/20 16:17	Dismantled Parts		Load JPG	☒
85	11/05/20 16:17	Dismantled Parts		Load JPG	☒
86	11/05/20 16:17	Dismantled Parts		Load JPG	☒
87	11/05/20 16:17	Dismantled Parts		Load JPG	☒
88	11/05/20 16:17	Dismantled Parts		Load JPG	☒
89	11/05/20 16:17	Dismantled Parts		Load JPG	☒
90	11/05/20 16:17	Dismantled Parts		Load JPG	☒
91	11/05/20 16:17	Dismantled Parts		Load JPG	☒
92	11/05/20 16:17	Dismantled Parts		Load JPG	☒
93	11/05/20 16:17	Dismantled Parts		Load JPG	☒

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	11/05/20 16:17	Dismantled Parts		Load JPG	☒
95	11/05/20 16:17	Dismantled Parts		Load JPG	☒
96	11/05/20 16:17	Dismantled Parts		Load JPG	☒
Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/03/20 15:48	EMAIL FROM AIG TO ARRANGE FOR SURVEY		Load PDF	
2	27/03/20 15:48	TP GIA REPORT		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	30/03/20 12:51	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20004594/QTD3S2**Date:** 14/05/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100444699
Claimant Vehicle No :	SJV2111R	Insured Vehicle No :	GBE5233L
Date of Loss:	26/03/2020	Nature of Claim:	TP
		Claim No:	7817890920SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV2111R	Engine No:	K24A65002807
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRB18508C202806
Reg. Date:	05/02/2008 (Man. Year: 2007)	Odometer:	22626 km
Colour:	Beige		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/03/2020		
Date Inspected:	27/03/2020	Inspected At:	Elites Performance (HQ) 51 DEFU LANE 9 Singapore 539291
Estimated Period of Repair:	3.0 days		

Adjuster: OI SUN PIN**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Dented	0.00 F	*- F
2	1		*FRT LH DOOR GARNISH OUTER	Scratched	0.00 F	*- F
3	1		*FRT LH DOOR GLASS OUTER MOULDING	Necessary	0.00 F	*- F
4	1		*FRT LH DOOR GLASS	Crushed	0.00 F	*- F
5	1		*FRT LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
6	1		*FRT LH DOOR CENTRAL LOCK	Jammed	0.00 F	*- F
7	1		*FRT LH DOOR CHECKER	Bent	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >