

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD20004599/ASD3E2

Date: 20/05/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.

Policy No:

PNPV2018-00009395-01

Claimant Vehicle No : SFF1134M

Insured Vehicle No : SGK786A

Date of Loss: 22/03/2020

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFF1134M**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ3218327

Reg. Date: 13/01/2009 (Man. Year: 2008)

Chassis No: JTDER12W503001517

Colour: Black

Odometer: 170853 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,982.00	828.75	1,153.25	58.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	790.00	930.00	54.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,702.00	1,618.75	2,083.25	56.27
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	3,702.00	1,300.00	2,402.00	64.88

INSPECTION

Date of Assignment: 27/03/2020

Date Inspected: 30/03/2020 Inspected At:

Jec Automotive (HQ)

1 KAKI BUKIT AVENUE 6, #02-11

AUTOBAY

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 May 2020)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFF1134M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	545.00 F	*545.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER LH	Necessary	58.00 F	*58.00 FL
4	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
5	1		*TAILLAMP LH	Cut	472.00 F	*472.00 FL
6	1		*REAR END PANEL	Repair	597.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,982.00	1,105.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	276.25
Total Parts (\$\$)	1,982.00	828.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	250.00
2	SPRAY PAINTING	New	700.00	400.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	120.00	0.00
Gross Labour Cost (S\$)			1,720.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >