



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : ODVehicle No. : SLE1570XMake & Model : HYUNDAI TUCONYear of Manufacture : 2016Chassis No. : KMHJ3813MHU273606Ins Company : ALLIED WORLD

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 22/03/2020Time of Accident : 19:00

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**Parts (a) Cost / List Price Items \$ 2,582.30Plus/Less 10% \$ 258.23Total of Cost / List \$ 2,840.53(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 2,840.53Labour (Appendix B) \$ 2,930.00Total Repair Cost \$ 5,770.53

Case Owner \_\_\_\_\_

Signature \_\_\_\_\_

Contact No \_\_\_\_\_

68485725 JOHARI

Steve (LKK)

8322 8813

OD - NM AUL (Rental)

Excess - ?

9 days

P/P

My BL sy

6/4/20, 12.00pm

The above total will be subjected to 7% G.S.T.

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_