Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004625/KGA3Q2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900118835 Claimant SMP4187E Insured Vehicle No: SGT15U

Vehicle No:

Date of Loss: 26/03/2020 Nature of Claim: ΤP Claim No: 1923926721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMP4187E Reg No:

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) Engine No: 2ZR0D97664 Reg. Date: 25/09/2019 (Man. Year: 2019) Chassis No: ZWR800395289 Colour: Metallic Black Odometer: 29778 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Rear Left Side: Front Left Side: Goodyear 8 mm Goodyear 6 mm Front Right Side: Rear Right Side: Goodyear 6 mm Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,203.84	963.95	239.89	19.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	800.00	800.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,803.84	1,763.95	1,039.89	37.09
+ GST 7.00/7.00% (S\$)	196.27	123.48	72.79	37.09
Nett Amount (S\$)	3,000.11	1,887.43	1,112.68	37.09
+ Loss of Use (3.0 x S	S\$92.00/day) (S\$)	276.00		
+ Doc	2.00			

INSPECTION

Date of Assignment: 01/04/2020

Date Inspected: 01/04/2020 Optima Werkz Pte Ltd (HQ) Inspected At:

Nett Liability (S\$)

6 Kung Chong Road Singapore 159143

2,165.43

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	974.60 FL	*730.95 F
2	1		*REAR BUMPER CLIPS (8 PCS)	Necessary	44.00 FL	*33.00 F
3	1		*REAR TAILGATE HYBRID EMBLEM	Serviceable	48.70 FL	*- F
4	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- F
5	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- F
6	1		*REAR BUMPER REVERSE SENSOR	Necessary	350.00 FS	*200.00 FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	1,417.30	963.95
			- List Item Discount on L Items 2	20.00/0.00% (S\$) _	213.46	0.00
				Total Parts (S\$)	1,203.84	963.95
			Report was unsubmitted during the	nis print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	LABOUR CHARGES TO REMOVE,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	300.00					
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC	New	900.00	450.00					
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC .TO EFFECT REPLACE OF REAR BUMPER	New	80.00	50.00					
4	TO DIAGNOSE FAULT CODE & RESET MEMORY	New	120.00	0.00					
	Gross Labour Cost (S\$)		1,600.00	800.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >