

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004626/AGA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100274774
Claimant
Vehicle No : SLF9358K **Insured Vehicle No :** SKC7295Z
Date of Loss: 26/03/2020 **Nature of Claim:** TP **Claim No:** 4539820215SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF9358K**
 Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN017094
 Reg. Date: 15/09/2016 (Man. Year: 2016) Chassis No: WAUZZZF45HA020890
 Colour: Brown Odometer: 53475 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,745.00	355.20	4,389.80	92.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,247.00	1,957.20	5,289.80	72.99
+ GST 7.00/7.00% (S\$)	507.29	137.00	370.29	72.99
Nett Amount (S\$)	7,754.29	2,094.20	5,660.09	72.99
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,276.20		

INSPECTION

Date of Assignment: 31/03/2020
 Date Inspected: 31/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,079.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	210.00 FS	*168.00 FS
4	1		*REAR BUMPER SPOILER	Cut	234.00 FS	*187.20 FS
5	1		*REAR LIGHT REFLECTOR -RH REAR	Not Necessary	39.00 FS	*- FS
6	1		*LED TAIL LIGHT -RH	Not Necessary	959.00 FS	*- FS
7	1		*TAIL LIGHT TRIM -RH	Not Necessary	28.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
9	2		*REAR BUMPER CARRIER SEAL	Not Necessary	26.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	42.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*- FS
12	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,745.00** **355.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >