

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004627/EBA3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070010760

Claimant
Vehicle No : SMR3522S **Insured Vehicle No :** SGP6388A

Date of Loss: 27/03/2020 Nature of Claim: TP Claim No: 4097649041SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3522S		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD885281
Reg. Date:	30/12/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF35L1022509
Colour:	Blue	Odometer:	1405 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,210.00	4,977.36	5,232.64	51.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,392.00	5,962.00	5,430.00	47.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,602.00	10,939.36	10,662.64	49.36
+ GST 7.00/7.00% (S\$)	1,512.14	765.76	746.38	49.36
Nett Amount (S\$)	23,114.14	11,705.12	11,409.02	49.36
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,187.12		

INSPECTION

Date of Assignment: 01/04/2020

Date Inspected: 01/04/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Repair	1,397.00 FS	*- FS
2	1	*REAR BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	1	*REAR BUMPER SPOILER	Not Necessary	433.00 FS	*- FS
4	1	*REAR BUMPER CROSS REINFORCEMENT -CENTRE	Not Necessary	91.00 FS	*- FS
5	1	*REAR LIGHT REFLECTOR -RH	Not Necessary	39.00 FS	*- FS
6	2	*REAR WHEEL COVER -LH /RH	Necessary	506.00 FS	*404.80 FS
7	1	*REAR DOOR -RH	Dented	2,512.00 FS	*2,009.60 FS
8	1	*REAR DOOR OUTER SEAL -RH	Necessary	127.00 FS	*101.60 FS
9	1	*REAR DOOR ATTACHMENT PARTS	Not Necessary	293.00 FS	*- FS
10	1	*REAR DOOR CATCH	Not Necessary	113.00 FS	*- FS
11	1	*DOOR HINGE HALF UPPER PART-RH UPPER	Not Necessary	42.00 FS	*- FS
12	1	*HINGE HALVES -RH UPPER	Not Necessary	43.00 FS	*- FS
13	1	*DOOR HINGE HALF UPPER PART -RH LOWER	Not Necessary	45.00 FS	*- FS
14	1	*DOOR HINGE HALF LOWER PART -RH LOWER	Not Necessary	42.00 FS	*- FS
15	1	*REAR DOOR COVER -RH	Scratched	242.00 FS	*193.20 FS
16	1	*FRONT DOOR -RH	Dented	2,422.00 FS	*1,937.60 FS
17	1	*FRONT DOOR OUTER SEAL -RH	Necessary	156.00 FS	*124.80 FS
18	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	148.00 FS	*- FS
19	1	*FRONT DOOR CATCH	Not Necessary	113.00 FS	*- FS
20	1	*FRONT DOOR COVER -RH	Scratched	253.00 FS	*202.40 FS
21	1	*REAR ALUMINIUM RIM-RH	Not Necessary	893.00 FS	*- FS
22	1	*SUNDRIES	Necessary	300.00 FS	*3.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **10,210.00** **4,977.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR RHS B-PILLAR	New	800.00	500.00
2	TO RESPRAY RHS B-PILLAR	New	1,000.00	550.00
3	TO RESPRAY FRONT DOOR RH AND REAR DOOR RH HANDLES	New	600.00	100.00
4	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
5	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	560.00	560.00
6	TO DISMANTLE RHS FRONT DOOR PANEL TRIM ,TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	400.00	0.00
7	TO DISMANTLE AND RENEW REAR BUMPER ,RHS REAR DOOR AND RHS FRONT DOOR .TO REPAIR RHS REAR FENDER RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
8	TO RESPRAY REAR BUMPER ,RHS REAR FENDER ,RHS REAR DOOR AND RHS FRONT DOOR	New	4,000.00	2,200.00
9	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,392.00	5,962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >