

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20004635/R1TF3E2

Date: 29/07/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30746019000
Claimant Vehicle No :	SKT13C	Insured Vehicle No :	GBD4026E
Date of Loss:	20/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201526

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT13C		
Make & Model:	MERCEDES-BENZ GLA45 AMG, 2.0 4MATIC (A)	Engine No:	13398080039279
Reg. Date:	10/09/2015 (Man. Year: 2015)	Chassis No:	WDC1569522J150655
Colour:	Grey	Odometer:	94368 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35Z R20	Rear Tyre Size:	255/35Z R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,774.98	2,188.80	3,586.18	62.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	2,340.00	800.00	25.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,914.98	4,528.80	4,386.18	49.20
+ GST 7.00/7.00% (S\$)	624.05	317.02	307.03	49.20
Nett Amount (S\$)	9,539.03	4,845.82	4,693.21	49.20

INSPECTION

Date of Assignment:	07/04/2020	
Date Inspected:	02/04/2020 Inspected At:	5 Soon Lee Street #01-62 Repairer : Cycle & Carriage Industries Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2020)
Parts:	M1-SUV	MERCEDES-BENZ GLA45 AMG 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT13C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REG. PLATE WITH HOUSING	Not Necessary	60.00 FS	*- FS
2	1		*RH//F HEADLAMP	Serviceable	2,885.53 FS	*- FS
3	1		*FRT BUMPER	Deformed	1,763.08 FS	*1,763.08 FS
4	1		*CT/F IMPACT ABSORBER	Serviceable	142.02 FS	*- FS
5	1		*CT/F BASIC MOUNTING FOR BUMPER	Serviceable	164.95 FS	*- FS
6	1		*RADIATOR GRILLE STAR	Scratched	136.49 FS	*136.49 FS
7	1		*FRT CROSS MEMBER	Serviceable	333.68 FS	*- FS
8	1		*FRT BUMPER STICKER	Necessary	289.23 FS	*289.23 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **5,774.98** **2,188.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	0.00
3	REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
4	RESPRAY FRONT BUMPER	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			3,140.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >