

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20004641/KVF3E2
Date: 08/07/2020

REFERENCE

| | | |
|--|-----------------------------|---------------------|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 29139332 |
| Claimant Vehicle No : GBH5998Y | Insured Vehicle No : | EQ180P |
| Date of Loss: 24/03/2020 | Nature of Claim: | TP Claim No: 622517 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|----------------------------------|--------------------|-----------------------------------|
| Reg No: | GBH5998Y | Engine No: | K9KE628D376343 |
| Make & Model: | NISSAN NV200 ACENTA, 1.5 DCI (A) | Chassis No: | VSKYBAM20U0153530 |
| Reg. Date: | 26/07/2018 (Man. Year: 2017) | Odometer: | 52315 km |
| Colour: | White | Engine Capacity: | 1461 cc |
| Market Value/New Car Price: | N/A | Sum Insured (S\$): | Market Value/New Car Price |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|--------------|
| Front Tyre Size: | 175/70 R14 | Rear Tyre Size: | 175/70 R14 |
| Front Left Side: | Goodyear 4 mm | Rear Left Side: | Pirelli 3 mm |
| Front Right Side: | Goodyear 4 mm | Rear Right Side: | Pirelli 3 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|---------------|--------------|
| Parts | 1,989.64 | 1,580.91 | 408.73 | 20.54 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 850.00 | 700.00 | 150.00 | 17.65 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,839.64 | 2,280.91 | 558.73 | 19.68 |
| + GST 7.00/7.00% (S\$) | 198.77 | 159.66 | 39.11 | 19.68 |
| Nett Amount (S\$) | 3,038.41 | 2,440.57 | 597.84 | 19.68 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 30/03/2020 | |
| Date Inspected: | 09/06/2020 | Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 08 Jul 2020) | |
| Parts: | N/A | NISSAN NV200 ACENTA 1.5 DCI (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBH5998Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|--------------|------------|-----------|
| 1 | 1 | | *FRONT BUMPER | Bent | 655.20 FN | *589.68 F |
| 2 | 1 | | *FRONT BUMPER SIDE RETAINER RH | Distorted | 25.40 FN | *22.86 F |
| 3 | 6 | | *FRONT BUMPER CLIP | Necessary | 30.00 FN | *27.00 F |
| 4 | 1 | | *FRONT BUMPER FOG LAMP GARNISH RH | No such part | 96.80 FN | *- F |
| 5 | 1 | | *HEADLAMP RH | Cut | 444.63 FN | *400.16 F |
| 6 | 1 | | *RH HEADLAMP LOWER GARNISH | Mtg Cracked | 368.50 FN | *331.65 F |
| 7 | 1 | | *FRT RH FENDER INNER SHIELD | Cracked | 188.40 FN | *169.56 F |
| 8 | 2 | | *COMPANY STICKER | Necessary | 40.00 FS | *40.00 FS |
| 9 | 1 | | *FRONT BUMPER FOG LAMP RH | Serviceable | 321.60 FS | *- FS |

F=Franchise part. S=SpcNett. N=NettItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (S\$) | 2,170.53 | 1,580.91 |
| - Nett Item Discount on N Items 10.00/0.00% (S\$) | 180.89 | 0.00 |
| Total Parts (S\$) | 1,989.64 | 1,580.91 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|---------------------------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REFIXD FRT BUMPER ASSY,FOG LAMPS,HEADLAMP AND LOWER COVER,KNOCK AND REPAIR FRT BUMPER REINFORCEMENT,FRT RH FENDER AND RE-ALIGN THE SAME | New | 500.00 | 400.00 |
| 2 | TO PUTTY AND RESPRAY ON FRT RH FENDER,RH HEADLAMP LOWER COVER | New | 350.00 | 300.00 |
| | | | Gross Labour Cost (\$\$) | 700.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >