



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005539
INV Date 13/08/2020
Reference CC4/LPC20004649/T1ds3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SMK 2984K
Insured Veh. SLF 4423M
Claim No. 20/20/20/VP05/023183
Policy No. Z20VP05026069
Accident Date 10/03/2020
Inspection Date 30/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20004649/T1ds3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 13-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 4423M	Veh. Inspected	SMK 2984K
Policy No.	Z20VP05026069	Coverage (\$)	0.00
Claim No.	20/20/20/VP05/023183	Excess (\$)	0.00
Assign From	KENNY	Assign Date	26/03/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHMGK3850KS211544	Colour	BLACK
Odometer	5356	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	175/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/03/2020	Inspection Date	30/03/2020
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 2984K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	NUMBER PLATE WITH CASING -OPC-L (SN)	NECESSARY	45.00	45.00
1	FACE ,FR.BUMPER (SN)	DEFORMED	388.27	388.27
1	BEAM UPPER ,L.FR.BUMPER (SN)	NOT NECESSARY	21.30	-
1	GARNISH,L.FR.BUMPER (SN)	MISSING	22.27	22.27
19	CLIP,BUMPER (SN)	NECESSARY	32.77	32.77
1	SPACERL.FR.BUMPER (SN)	NECESSARY	7.80	7.80
1	HEADLIGHT ASSY ,L (SN)	CUT	369.07	369.07
1	PANEL,L.FR.FENDER (SN)	TO REPAIR SEE LABOUR	306.67	-
1	BRACKET COMP,L.FR.FENDER (SN)	NOT NECESSARY	32.10	-
1	FENDER ASSY ,L.FR.INNER (SN)	NOT NECESSARY	56.70	-
1	ENCLOSURE ,L.FR.FENDER (SN)	NOT NECESSARY	13.50	-
1	EXTENSION SETL.FR (SN)	NOT NECESSARY	72.60	-
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			1,468.05	895.18
	<u>LABOUR</u>			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		180.00	180.00
	CUT & RENEW EXTENSION AND RENEW DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF PANEL,L.FR.FENDER .		3,000.00	1,300.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,500.00	1,560.00
	REMOVE AND RE-SEAL OF OPC PLATE.		650.00	650.00
			6,330.00	3,690.00
	GRAND TOTAL		7,798.05	4,585.18
	RECOMMENDED COST OF REPAIRS			4,585.18

Report Ref No. CC4/LPC20004649/T1ds3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 2984K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 2984K

RE-INSPECTION

