

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20004656/UBA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJR4121U	Insured Vehicle No :	SHC8675P
Date of Loss: 27/03/2020	Nature of Claim: TP	Claim No: MCT20030471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR4121U	
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No: 1NZX922732
Reg. Date:	23/06/2009 (Man. Year: 2009)	Chassis No: MR053HY9305117420
Colour:	Red	Odometer: 173646 km
Engine Capacity:	1497 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,799.90	3,054.55	6,745.35	68.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,950.00	2,100.00	51.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,849.90	5,004.55	8,845.35	63.87
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	13,849.90	4,000.00	9,849.90	71.12
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,400.00		

INSPECTION

Date of Assignment:	30/03/2020	
Date Inspected:	30/03/2020	Inspected At: Choo Motor Spray Painter 1 Kaki Bukit Ave 6, #01-39 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2020)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR4121U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	765.10 F	*646.10 FL
2	1		*BOOTLID REAR LOGO	Necessary	68.50 F	*68.50 FL
3	1		*BOOTLID VIOS EMBLEM	Necessary	62.20 F	*52.50 FL
4	1		*BOOTLID E EMBLEM	Necessary	60.50 F	*45.00 FL
5	1		*BOOTLID OUTER HANDLE	Not Necessary	261.10 F	*- FL
6	1		*BOOTLID INNER LOCK	Twisted	199.20 F	*199.20 FL
7	1		*BOOTLID LOCKER STICKER	Not Necessary	68.80 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	266.40 F	*266.40 FL
9	2		*BOOTLID HINGES	Not Necessary	291.00 F	*- FL
10	1		*REAR BUMPER	Dented	665.40 F	*468.20 FL
11	1		*REAR BUMPER REFLECTOR O/S	Cracked	182.30 F	*161.10 FL
12	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	137.00 F	*45.50 FL
13	1		*REAR BUMPER BRACKET O/S	Not Necessary	88.50 F	*- FL
14	1		*REAR BUMPER SPLASH SHIELD O/S	Not Necessary	142.30 F	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
16	1		*REAR END PANEL	Dented / Bent	688.20 F	*604.10 FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	241.30 F	*241.30 FL
18	1		*REAR FLOOR PANEL	Repair	911.20 F	*- FL
19	1		*REAR FLOOR PANEL TOP BOARD	Torn	266.30 F	*266.30 FL
20	1		*REAR FLOOR PANEL TOOLS SPONGES	N/S Torn	606.20 F	*303.10 FL
21	1		*REAR EXHAUST BOX	Not Necessary	581.10 F	*- FL
22	2		*REAR EXHAUST BOX MOUNTING	Not Necessary	90.00 F	*- FL
23	1		*TAILLAMPS	N/S Cracked	998.20 F	*322.10 FL
24	1		*TAILLAMP HOUSING PANEL O/S	Repair	265.50 F	*- FL
25	1		*REAR FENDER O/S	Not Necessary	845.10 F	*- FL
26	1		*REAR FENDER INNER TRIM O/S	Not Necessary	288.50 F	*- FL
27	1		*SET REAR FENDER INNER TRIM CLIPS O/S	Not Necessary	50.00 F	*- FL
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
30	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 F	*- FL
31	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 F	*- FL
32	1		*REAR EXHAUST CHROME	Not Necessary	80.00 F	*- FL
33	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	150.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,799.90	3,989.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	934.85
Total Parts (\$\$)	9,799.90	3,054.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
3	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	New	150.00	80.00
4	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	120.00	60.00
8	LABOUR FOR PANEL BEATING CUT ,WELD ,STRAIGHTEN & REPLACING PARTS	New	1,500.00	680.00
9	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			4,050.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >