

PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2020)
Parts: 143	MERCEDES-BENZ C180 1.6 EXCLUSIVE R17 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK5675H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	3,793.00 F	*- FL
2	1		*FRONT HEADLAMP RH	Cracked	4,852.00 F	*3,005.85 FL
3	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	390.00 F	*- FL
4	1		*FRONT GRILLE BASE	Not Necessary	977.00 F	*- FL
5	1		*FRONT GRILLE CHROME	Not Necessary	1,520.00 F	*- FL
6	1		*FRONT BUMPER	Deformed / Cut	2,921.00 F	*1,632.22 FL
7	2		*FRONT BUMPER RETAINER L+R	Not Necessary	392.00 F	*- FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	136.00 F	*- FL
9	1		*SET FRONT BUMPER SENSOR	Shorted (1 PCS ONLY)	1,788.00 F	*245.00 FL
10	1		*FRONT BUMPER SENSOR CONTROL MODULE	Not Necessary	1,265.00 F	*- FL
11	1		*FRONT BUMPER GRILLE	Not Necessary	895.00 F	*- FL
12	1		*FRONT BUMPER LOWER CHROME	Not Necessary	750.00 F	*- FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	637.00 F	*- FL
14	1		*FRONT BUMPER UNDERCOVER	Not Necessary	519.00 F	*- FL
15	2		*FRONT FENDER L+R	Not Necessary	3,262.00 F	*- FL
16	2		*FRONT FENDER COWLING L+R	Not Necessary	538.00 F	*- FL
17	1		*FRONT SUPPOT PANEL	Not Necessary	3,402.00 F	*- FL
18	1		*FRONT SUPPOT PANEL TOP GARNISH	Not Necessary	613.00 F	*- FL
19	1		*FRONT AIR CON CONDENSOR	Not Necessary	2,573.00 F	*- FL
20	1		*HIGH PRESSURE HOSE	Not Necessary	670.00 F	*- FL
21	1		*LOW PRESSURE HOSE	Not Necessary	658.00 F	*- FL
22	1		*RADIATOR	Not Necessary	3,107.00 F	*- FL
23	1		*SUCTION PIPE	Not Necessary	524.00 F	*- FL
24	1		*DISCHARGE PIPE	Not Necessary	535.00 F	*- FL
25	1		*FRONT NUMBER PLATE	Not Necessary	120.00 FS	*- FS
26	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
27	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
28	10		*FRONT BONNET ISULATOR CLIPS	Not Necessary	120.00 FS	*- FS
29	10		*FRONT FENDER COWLING CLIPS	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	37,247.00	4,933.07
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	488.31
Total Parts (\$\$)	37,247.00	4,444.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS , CUT /WELD ,KNOCK & REALIGN	New	1,500.00	200.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,500.00	200.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	300.00	0.00
4	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	400.00	50.00
5	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	New	120.00	0.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	120.00	20.00
7	TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE	New	1,200.00	0.00
8	TO DO WATER LEAK TEST	New	120.00	0.00
9	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	New	120.00	0.00
			Gross Labour Cost (\$)	470.00
			5,380.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >