

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20004665/DGA3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0002942
Claimant Vehicle No :	SHC2980Y	Insured Vehicle No :	SKU179C
Date of Loss:	26/03/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0000733

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2980Y		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU192207
Reg. Date:	12/03/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU141506
Colour:	Blue	Odometer:	172684 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,297.20	8,348.60	7,948.60	48.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,440.00	1,930.00	57.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	19,667.20	9,788.60	9,878.60	50.23
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (8.0 x S\$117.95/day) (S\$)		943.60		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		11,089.20		
Global Sum Settlement (S\$)		11,100.00		

INSPECTION

Date of Assignment: 30/03/2020

Date Inspected: 31/03/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming
Industrial Estate
Singapore 575644

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jul 2020)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2980Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Serviceable	187.40 FL	*- FL
3	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
4	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
6	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
7	1		*REAR SPOILER	Not Necessary	665.40 FL	*- FL
8	2		*BOOT LID LAMP (LH/RH)	Cracked	1,588.80 FL	*1,588.80 FL
9	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
10	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
11	1		*BOOT LID TRIMBOARD ,CENTRE	Not Necessary	159.60 FL	*- FL
12	1		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	92.50 FL	*- FL
13	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
14	1		*BOOT LID GLASS ,LOWER	Shattered	584.90 FL	*584.90 FL
15	1		*REAR WINDSCREEN MOULDING	Not Necessary	137.60 FL	*- FL
16	1		*REAR BUMPER	Dented	459.40 FL	*459.40 FL
17	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent / Broken	376.20 FL	*376.20 FL
19	1		*ANTENNA ASSY -SMARTK	Broken	689.50 FL	*689.50 FL
20	1		*REAR BUMPER CENTRE MOULDING ASSY	Dented	451.25 FL	*451.25 FL
21	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Serviceable	47.50 FL	*- FL
22	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
23	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Not Necessary	171.60 FL	*- FL
24	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
25	1		*REAR BUMPER UNDER CENTRE	Not Necessary	123.85 FL	*- FL
26	2		*REAR BUMPER SIDE UNDER (LH/RH)	Not Necessary	246.20 FL	*- FL
27	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
28	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
29	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
30	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	2		*LICENCE LAMP (LH/RH)	Not Necessary	170.60 FL	*- FL
32	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
33	2		*TAIL LAMP (LH/RH)	Mtg Cracked	1,740.80 FL	*1,740.80 FL
34	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	417.80 FL	*- FL
35	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
36	1		*ANTENNA ASSY -TRUNK	Not Necessary	689.50 FL	*- FL
37	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
38	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
39	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
40	1		*SPARE TYRE PANEL	Not Necessary	892.50 FL	*- FL
41	1		*MEMBER ASSY -REAR FLOOR CENTRE	Not Necessary	863.50 FL	*- FL
42	2		*PANEL ASSY -REAR FLOOR SIDE (LH/RH)	Not Necessary	78.80 FL	*- FL
43	1		*REAR TRAY TOOLS BOX RH	Not Necessary	675.30 FL	*- FL
44	1		*REAR TRAY TOOLS BOX LH	Not Necessary	693.20 FL	*- FL
45	1		*REAR TRAY LUGGS CENTER	Not Necessary	354.20 FL	*- FL
46	1		*EXHAUST PIPE INSULATOR	Not Necessary	235.00 FL	*- FL
47	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL
48	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
49	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	35.00 FS	*16.60 FS
50	1		*BOOT LID COMFORT CABLINK TEL NO.STICKER	Not Necessary	30.00 FS	*- FS
51	1		*REAR NO PLATE +TRIM COVER	Cracked	45.00 FS	*45.00 FS
52	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
53	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
54	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
55	1		*SPARE TYRE PANEL TOP COVER SILICON	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,201.00	10,339.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,903.80	1,991.25
Total Parts (\$\$)	16,297.20	8,348.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	600.00
2	SPRAY PAINTING CHARGE	New	1,200.00	600.00
3	WIRING CHARGE	New	80.00	0.00
4	TUFF KOTE	New	140.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE /REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
Gross Labour Cost (\$)			3,370.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >