



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2003395  
INV Date 23/04/2020  
Reference CS/SMO20004668/Ksd3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. GBA 7735M  
Insured Veh. SLN 9828D  
Claim No. CMTD2001305/MYE  
Policy No.  
Accident Date 26/03/2020  
Inspection Date 01/04/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20004668/Ksd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 23-04-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLN 9828D	Veh. Inspected	GBA 7735M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2001305/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	30/03/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI CANTER	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	FB70BBA10363	Colour	WHITE	
Odometer	369267	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	YOKOHAMA	2 mm	
L/H Front Tyre	195 R15X8	YOKOHAMA	2 mm	
R/H Rear Tyre	195 R15X8 (D)	BRIDGESTONE	3/3 mm	
L/H Rear Tyre	195 R15X8 (D)	BRIDGESTONE	3/3 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/03/2020	Inspection Date	01/04/2020	
Survey held at	AE AUTO PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 7735M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE	BENT	2,850.00	2,398.00
1	REAR DECK END PANEL	TO REPAIR SEE LABOUR	980.00	-
1	FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
2	TAILLAMPS	SCRATCHED	960.00	576.00
2	TAILLAMP BRACKETS	TO REPAIR SEE LABOUR	440.00	-
1	SET SPARE TYRE BRACKETS	BENT	385.00	336.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	840.00	-
1	REAR CENTER BEAM	TO REPAIR SEE LABOUR	1,285.00	-
	LESS 20% DISCOUNT		-1,548.00	-662.00
			6,192.00	2,648.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	70KM/H (SN)	NECESSARY	60.00	15.00
1	7 PAX STICKER (SN)	NECESSARY	200.00	15.00
1	REAR NO PLATE (SN)	BENT	90.00	25.00
1	SPARE TYRE (SN)	SERVICEABLE	550.00	-
			900.00	55.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REPLACE REPAIR,PULL CHASSIS,ALIGN,ADJUST.INCLUSIVE OF THE REPAIR OF REAR DECK END PANEL,FLOOR PANEL,REAR CENTER BEAM,TAILLAMP BRACKETS AND REAR EXHAUST.		1,000.00	450.00
	TO DO SPRAY PAINTING ON AFFECTED AREA.		1,000.00	400.00
	TO DO REAR DECK BODY ALIGNMENT.	NOT NECESSARY	350.00	-
	TO CHECK WIRING SYSTEM.		120.00	20.00
	ANTI RUST.	NOT NECESSARY	120.00	-
			2,590.00	870.00
	<b>GRAND TOTAL</b>		<b>9,682.00</b>	<b>3,573.00</b>

Report Ref No. CS/SMO20004668/Ksd3n2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,600.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO20004668/Ksd3n2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 7735M

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 7735M

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. GBA 7735M**

**RE-INSPECTION**

