

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20004674/UGA3Q2

Date: 19/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLP5447K	Insured Vehicle No :	SHD3362U
Date of Loss: 29/03/2020	Nature of Claim: TP	Claim No: MCT20030502

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5447K		
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Engine No:	1NZR471851
Reg. Date:	08/06/2017 (Man. Year: 2016)	Chassis No:	NHP1707072137
Colour:	Brown	Odometer:	65258 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,099.50	687.69	411.81	37.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	725.00	375.00	350.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,824.50	1,062.69	761.81	41.75
Approved Total (Overridden) (S\$)		850.00		
(S\$)	1,824.50	850.00	974.50	53.41
+ GST 7.00/7.00% (S\$)	127.72	59.50	68.22	53.41
Nett Amount (S\$)	1,952.22	909.50	1,042.72	53.41
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,130.95		
Global Sum Settlement (S\$)		1,130.00		

INSPECTION

Date of Assignment:	30/03/2020	
Date Inspected:	30/03/2020 Inspected At:	NPH Auto Service (HQ)
		Blk 9005 Tampines Steet 93, #01-246/254
		Singapore 528839
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP5447K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FOG LAMP OUTER PROTECTOR	Grazed	112.50 FL	*112.50 FL
2	1		*FRONT FOG LAMP	Not Necessary	355.00 FL	*- FL
3	1		*FRONT BUMPER	Dented / Cut	950.40 FL	*804.42 FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	48.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,466.00	916.92
- List Item Discount on L Items 25.00/25.00% (\$\$)	366.50	229.23
Total Parts (\$\$)	1,099.50	687.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL F/BUMPER ,F/BUMPER FOG LAMP ,F/HEADLAMP ,KNOCK HEADLAMP SUPPORT PANEL AND RESTRIAHGTEN BODY	New	300.00	150.00
2	SPRAY PAINTING	New	400.00	200.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
Gross Labour Cost (\$\$)			725.00	375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >