

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20004696/T1YF3E2

Date: 22/09/2020

REFERENCE

Insured/Claimant: FOO SIN KWANG(FU XINGGUANG)

Policy No: 1800126812

Date of Loss: 24/03/2020

Nature of Claim: OD

Claim No: 7135644789SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF1690R**

Make & Model: AUDI A3, 1.4 TFSI (A)

Engine No: CZE836377

Reg. Date: 30/10/2018 (Man. Year: 2018)

Chassis No: WAUZZZ8V4K1002295

Colour: Grey

Odometer: 30555 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$92,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,960.00	3,557.20	18,402.80	83.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,352.00	2,652.00	2,700.00	50.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,312.00	6,209.20	21,102.80	77.27
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	26,712.00	5,609.20	21,102.80	79.00
+ GST 7.00/7.00% (\$\$)	1,869.84	392.64	1,477.20	79.00
Nett Amount (\$\$)	28,581.84	6,001.84	22,580.00	79.00

INSPECTION

Date of Assignment: 31/03/2020

Date Inspected: 30/03/2020 Inspected At:

281 ALEXANDRA ROAD

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,894.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	72.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	151.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	505.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	560.00 FS	*- FS
7	2		*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	306.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,070.40 FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	354.00 FS	*- FS
11	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	681.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	178.00 FS	*- FS
13	1		*FOAM FILLER PIECE COVER	Not Necessary	115.00 FS	*- FS
14	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
15	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
16	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	188.00 FS	*- FS
17	1		*SIGNAL HORN - RH LOW TONE	Not Necessary	188.00 FS	*- FS
18	1		*BONNET	Bent	2,988.00 FS	*2,390.40 FS
19	1		*BONNET ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
20	1		*BONNET EDGE PROTECTION	Necessary	26.00 FS	*20.80 FS
21	1		*BONNET CATCH HOOK	Not Necessary	84.00 FS	*- FS
22	2		*BONNET STRIKER - LH / RH	Not Necessary	208.00 FS	*- FS
23	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
24	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
25	2		*LED HEADLIGHT - LH / RH	Not Necessary	10,386.00 FS	*- FS
26	2		*LIFT CYLINDER - LH / RH	Not Necessary	268.00 FS	*- FS
27	1		*LIFT CYLINDER HOSE	Not Necessary	64.00 FS	*- FS
28	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	46.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
30	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
31	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **21,960.00** **3,557.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,352.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >