

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1735U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL, SIDE:L7, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	330.70	-
1	PANEL, SIDE:L10,W FRAME, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	980.40	-
1	PANEL, SIDE:L11, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	1,092.50	-
1	COVER, REAR TAIL LAMP, LH, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	974.70	-
			3,378.30	-
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL, SIDE:L7, FOR MAN A22 BUS, PANEL, SIDE:L10,W FRAME, FOR MAN A22 BUS, PANEL, SIDE:L11, FOR MAN A22 BUS AND COVER, REAR TAIL LAMP, LH, FOR MAN A22 BUS.		795.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		602.00	528.00
			1,397.00	1,058.00
GRAND TOTAL			4,775.30	1,058.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				850.00

Report Ref No. NS/INC20004698/Esv3e2



CHEN TSUE YEE
Automotive Assessor



K.K.LAU CPT(RET)
BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.