

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 796G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR FRT / RH (DISC 25%)	DENTED	894.40	670.80
1	BUMPER REAR (DISC 25%)	BROKEN	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	DOOR RR / RH (DISC 25%)	DENTED	954.50	715.88
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	HINGE LOWER RHF, DOOR	NOT NECESSARY	90.10	-
1	HINGE UPPER RHF, DOOR	NOT NECESSARY	80.50	-
1	CHECK ASSY, FR DOOR,	NOT NECESSARY	150.30	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	UNDER COVER RR SHIELD	NOT NECESSARY	63.90	-
1	DOOR LOCK RR/RH	NOT NECESSARY	709.30	-
1	MOULDING, RR DOOR WINDOW RH	NOT NECESSARY	69.20	-
1	TAPE OUT WIN FRAME RHR, DOOR	NOT NECESSARY	32.30	-
1	DOOR REGULATOR MOTOR REAR RH	NOT NECESSARY	947.80	-
1	DOOR REGULATOR SUB-ASSY, FRT / REAR RH	NOT NECESSARY	224.80	-
1	WEATHERSTRIP RHR DR, OPENING	NOT NECESSARY	229.70	-
1	DOOR WEATHERSTRIP RR/RH	NOT NECESSARY	171.20	-
1	WIRE RHR, DOOR	NOT NECESSARY	280.20	-
1	SPEAKER ASSY, REAR	NOT NECESSARY	181.20	-

Report Ref No. NS/INC20004699/Eqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER LINE RR/RH	NOT NECESSARY	141.30	-
1	TAIL LAMP RH	NOT NECESSARY	557.80	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL HUB REAR	NOT NECESSARY	489.40	-
1	MOULDING BODY, RH	NOT NECESSARY	673.60	-
1	MIRROR ASSY, RH	NOT NECESSARY	1,307.10	-
1	MIRROR LAMP RH	NOT NECESSARY	65.30	-
1	COVER, OUTER MIRROR, RH	NOT NECESSARY	107.40	-
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,484.20	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	742.20	593.76
1	DOOR LOCK RR/RH (DISC 25%)	BENT	709.30	531.98
1	DOOR REGULATOR SUB-ASSY, FRT / REAR RH (DISC 25%)	BENT	224.80	168.60
1	DOOR REGULATOR MOTOR REAR RH (DISC 10%)	JAMMED	947.80	853.02
			16,700.34	4,103.14
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER RR/RH AND WHEEL DISC.		1,195.00	1,000.00
	SPRAY PAINT.		2,412.00	1,000.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
			4,427.00	2,110.00

Report Ref No. NS/INC20004699/Eqf3e2





GRAND TOTAL 21,127.34 6,213.14

RECOMMENDED COST OF LUMP SUM REPAIRS		4,950.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC20004699/Eqf3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser