

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2020		01 Apr 2020 12:07 Edit Adj Rpt	S\$10,800.00 Edit Estimates	S\$10,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured: SM AUTOMOTIVE , Co. Reg. No.: -				
Vehicle Reg. No.: SJN4210S		Date of Loss: 27/03/2020 08:00 - :59 [133 Months and 11 Days From LTA Reg Date (Man Yr)]		
Claim Type: OD / SNM20D201523		Policy/Cover Note No.: DMPCSNA00014622001 (Comprehensive)		
		Excess: S\$1,000.00		
Repairer: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60, 640756 Kaki Bukit - Tel: 67479241				
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/04/2020]				
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
- CHINA_TAIPING (05/04/2020): Alert - Adj Mandate Approved (S\$16370.04) - SJN4210S - Claim Handler: Ben Tang - CHINA_TAIPING (01/04/2020): Alert - Adj Mandate Approved (S\$10213.54) - SJN4210S - Claim Handler: Ben Tang				
ALL ASSOCIATED TASKS ☐				View All Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group	Subject
Handler	Assigned By	Completed On	Created On	Done?
No results.				

Claim Documents

***SJN4210S (SNM20D201523)**

OD

Mar 27 2020 8:00AM

[SM AUTOMOTIVE]

SM Automotive

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Assessment Reports

1 per page ▼
 ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/04/20 12:46	Adjuster Immediate Advice		Load HTM	
2	03/04/20 16:25	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/04/20 12:47	General View		Load PDF	
2	03/04/20 16:15	Reinspection Photo (1)		Load PDF	
3	03/04/20 16:15	Reinspection Photo (2)		Load PDF	
4	17/04/20 19:41	General View		Load JPG	☒
5	17/04/20 19:41	General View		Load JPG	☒
6	17/04/20 19:41	General View		Load JPG	☒
7	17/04/20 19:42	General View		Load JPG	☒
8	17/04/20 19:42	General View		Load JPG	☒
9	17/04/20 19:42	General View		Load JPG	☒
10	17/04/20 19:42	General View		Load JPG	☒
11	17/04/20 19:42	General View		Load JPG	☒
12	17/04/20 19:42	General View		Load JPG	☒
13	17/04/20 19:42	General View		Load JPG	☒
14	17/04/20 19:42	General View		Load JPG	☒
15	17/04/20 19:42	General View		Load JPG	☒
16	17/04/20 19:42	General View		Load JPG	☒
17	17/04/20 19:42	General View		Load JPG	☒
18	17/04/20 19:42	General View		Load JPG	☒
19	17/04/20 19:42	General View		Load JPG	☒
20	17/04/20 19:42	General View		Load JPG	☒
21	17/04/20 19:42	General View		Load JPG	☒
22	17/04/20 19:42	General View		Load JPG	☒
23	17/04/20 19:42	General View		Load JPG	☒
24	17/04/20 19:42	General View		Load JPG	☒
25	17/04/20 19:42	General View		Load JPG	☒
26	17/04/20 19:42	General View		Load JPG	☒
27	17/04/20 19:42	General View		Load JPG	☒
28	17/04/20 19:42	General View		Load JPG	☒
29	17/04/20 19:42	General View		Load JPG	☒
30	17/04/20 19:42	General View		Load JPG	☒
31	17/04/20 19:42	General View		Load JPG	☒
32	17/04/20 19:42	General View		Load JPG	☒
33	17/04/20 19:42	General View		Load JPG	☒
34	17/04/20 19:42	General View		Load JPG	☒
35	17/04/20 19:42	General View		Load JPG	☒
36	17/04/20 19:42	General View		Load JPG	☒
37	17/04/20 19:42	General View		Load JPG	☒
38	17/04/20 19:42	General View		Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
39	17/04/20 19:42	General View		Load JPG	☒
40	17/04/20 19:42	General View		Load JPG	☒
41	17/04/20 19:42	General View		Load JPG	☒
42	17/04/20 19:42	General View		Load JPG	☒
43	17/04/20 19:42	General View		Load JPG	☒
44	17/04/20 19:42	General View		Load JPG	☒
45	17/04/20 19:42	General View		Load JPG	☒
46	17/04/20 19:42	General View		Load JPG	☒
47	17/04/20 19:42	General View		Load JPG	☒
48	17/04/20 19:42	General View		Load JPG	☒
49	17/04/20 19:42	General View		Load JPG	☒
50	17/04/20 19:42	General View		Load JPG	☒
51	17/04/20 19:42	General View		Load JPG	☒
52	17/04/20 19:42	General View		Load JPG	☒
53	17/04/20 19:42	General View		Load JPG	☒
54	17/04/20 19:42	General View		Load JPG	☒
55	17/04/20 19:42	General View		Load JPG	☒
56	17/04/20 19:42	General View		Load JPG	☒
57	17/04/20 19:42	General View		Load JPG	☒
58	17/04/20 19:42	General View		Load JPG	☒
59	17/04/20 19:42	General View		Load JPG	☒
60	17/04/20 19:42	General View		Load JPG	☒
61	17/04/20 19:42	General View		Load JPG	☒
62	17/04/20 19:42	General View		Load JPG	☒
63	17/04/20 19:42	General View		Load JPG	☒
64	17/04/20 19:42	General View		Load JPG	☒
65	17/04/20 19:42	General View		Load JPG	☒
66	17/04/20 19:42	General View		Load JPG	☒
67	17/04/20 19:42	General View		Load JPG	☒
68	17/04/20 19:42	General View		Load JPG	☒
69	17/04/20 19:42	General View		Load JPG	☒
70	17/04/20 19:42	General View		Load JPG	☒
71	17/04/20 19:42	General View		Load JPG	☒
72	17/04/20 19:43	Reinspection Photo		Load JPG	☒
73	17/04/20 19:43	Reinspection Photo		Load JPG	☒
74	17/04/20 19:43	Reinspection Photo		Load JPG	☒
75	17/04/20 19:43	Reinspection Photo		Load JPG	☒
76	17/04/20 19:43	Reinspection Photo		Load JPG	☒
77	17/04/20 19:43	Reinspection Photo		Load JPG	☒
78	17/04/20 19:43	Reinspection Photo		Load JPG	☒
79	17/04/20 19:43	Reinspection Photo		Load JPG	☒
80	17/04/20 19:43	Reinspection Photo		Load JPG	☒
81	17/04/20 19:43	Reinspection Photo		Load JPG	☒
82	17/04/20 19:43	Reinspection Photo		Load JPG	☒
83	17/04/20 19:43	Reinspection Photo		Load JPG	☒
84	17/04/20 19:43	Reinspection Photo		Load JPG	☒
85	17/04/20 19:43	Reinspection Photo		Load JPG	☒
86	17/04/20 19:43	Reinspection Photo		Load JPG	☒
87	17/04/20 19:43	Reinspection Photo		Load JPG	☒
88	17/04/20 19:43	Reinspection Photo		Load JPG	☒
89	17/04/20 19:43	Reinspection Photo		Load JPG	☒
90	17/04/20 19:43	Reinspection Photo		Load JPG	☒
91	17/04/20 19:43	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
92	17/04/20 19:43	Reinspection Photo		Load JPG	☒
93	17/04/20 19:43	Reinspection Photo		Load JPG	☒
94	17/04/20 19:43	Reinspection Photo		Load JPG	☒
95	17/04/20 19:43	Reinspection Photo		Load JPG	☒
96	17/04/20 19:43	Reinspection Photo		Load JPG	☒
97	17/04/20 19:43	Reinspection Photo		Load JPG	☒
98	17/04/20 19:43	Reinspection Photo		Load JPG	☒
99	17/04/20 19:43	Reinspection Photo		Load JPG	☒
100	17/04/20 19:43	Reinspection Photo		Load JPG	☒
101	17/04/20 19:43	Reinspection Photo		Load JPG	☒
102	17/04/20 19:43	Reinspection Photo		Load JPG	☒
103	17/04/20 19:43	Reinspection Photo		Load JPG	☒
104	17/04/20 19:43	Reinspection Photo		Load JPG	☒
105	17/04/20 19:43	Reinspection Photo		Load JPG	☒
106	17/04/20 19:43	Reinspection Photo		Load JPG	☒
107	17/04/20 19:43	Reinspection Photo		Load JPG	☒
108	17/04/20 19:43	Reinspection Photo		Load JPG	☒
109	17/04/20 19:43	Reinspection Photo		Load JPG	☒
110	17/04/20 19:43	Reinspection Photo		Load JPG	☒
111	17/04/20 19:43	Reinspection Photo		Load JPG	☒
112	17/04/20 19:43	Reinspection Photo		Load JPG	☒
113	17/04/20 19:43	Reinspection Photo		Load JPG	☒
114	17/04/20 19:43	Reinspection Photo		Load JPG	☒
115	17/04/20 19:43	Reinspection Photo		Load JPG	☒
116	17/04/20 19:43	Reinspection Photo		Load JPG	☒
117	17/04/20 19:43	Reinspection Photo		Load JPG	☒
118	17/04/20 19:43	Reinspection Photo		Load JPG	☒
119	17/04/20 19:43	Reinspection Photo		Load JPG	☒
120	17/04/20 19:43	Reinspection Photo		Load JPG	☒
121	17/04/20 19:43	Reinspection Photo		Load JPG	☒
122	17/04/20 19:43	Reinspection Photo		Load JPG	☒
123	17/04/20 19:43	Reinspection Photo		Load JPG	☒
124	17/04/20 19:43	Reinspection Photo		Load JPG	☒
125	17/04/20 19:43	Reinspection Photo		Load JPG	☒
126	17/04/20 19:43	Reinspection Photo		Load JPG	☒
127	17/04/20 19:43	Reinspection Photo		Load JPG	☒
128	17/04/20 19:43	Reinspection Photo		Load JPG	☒
129	17/04/20 19:43	Reinspection Photo		Load JPG	☒
130	17/04/20 19:43	Reinspection Photo		Load JPG	☒
131	17/04/20 19:43	Reinspection Photo		Load JPG	☒
132	17/04/20 19:43	Reinspection Photo		Load JPG	☒
133	17/04/20 19:43	Reinspection Photo		Load JPG	☒
134	17/04/20 19:43	Reinspection Photo		Load JPG	☒
135	17/04/20 19:43	Reinspection Photo		Load JPG	☒
136	17/04/20 19:43	Reinspection Photo		Load JPG	☒
137	17/04/20 19:43	Reinspection Photo		Load JPG	☒
138	17/04/20 19:43	Reinspection Photo		Load JPG	☒
139	17/04/20 19:43	Reinspection Photo		Load JPG	☒
140	17/04/20 19:43	Reinspection Photo		Load JPG	☒
141	17/04/20 19:43	Reinspection Photo		Load JPG	☒
142	17/04/20 19:43	Reinspection Photo		Load JPG	☒
143	17/04/20 19:43	Reinspection Photo		Load JPG	☒
144	17/04/20 19:43	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
145	17/04/20 19:43	Reinspection Photo		Load JPG	☒
146	17/04/20 19:43	Reinspection Photo		Load JPG	☒
147	17/04/20 19:43	Reinspection Photo		Load JPG	☒
148	17/04/20 19:43	Reinspection Photo		Load JPG	☒
149	17/04/20 19:43	Reinspection Photo		Load JPG	☒
150	17/04/20 19:43	Reinspection Photo		Load JPG	☒
151	17/04/20 19:43	Reinspection Photo		Load JPG	☒
152	17/04/20 19:43	Reinspection Photo		Load JPG	☒
153	17/04/20 19:43	Reinspection Photo		Load JPG	☒
154	17/04/20 19:43	Reinspection Photo		Load JPG	☒
155	17/04/20 19:43	Reinspection Photo		Load JPG	☒
156	17/04/20 19:43	Reinspection Photo		Load JPG	☒
157	17/04/20 19:43	Reinspection Photo		Load JPG	☒
158	17/04/20 19:43	Reinspection Photo		Load JPG	☒
159	17/04/20 19:43	Reinspection Photo		Load JPG	☒
160	17/04/20 19:43	Reinspection Photo		Load JPG	☒
161	17/04/20 19:43	Reinspection Photo		Load JPG	☒
162	17/04/20 19:43	Reinspection Photo		Load JPG	☒
163	17/04/20 19:43	Reinspection Photo		Load JPG	☒
164	17/04/20 19:43	Reinspection Photo		Load JPG	☒
165	17/04/20 19:43	Reinspection Photo		Load JPG	☒
166	17/04/20 19:43	Reinspection Photo		Load JPG	☒
167	17/04/20 19:43	Reinspection Photo		Load JPG	☒
168	17/04/20 19:43	Reinspection Photo		Load JPG	☒
169	17/04/20 19:43	Reinspection Photo		Load JPG	☒
170	17/04/20 19:43	Reinspection Photo		Load JPG	☒
171	17/04/20 19:43	Reinspection Photo		Load JPG	☒
172	17/04/20 19:43	Reinspection Photo		Load JPG	☒
173	17/04/20 19:43	Reinspection Photo		Load JPG	☒
174	17/04/20 19:43	Reinspection Photo		Load JPG	☒
175	17/04/20 19:43	Reinspection Photo		Load JPG	☒
176	17/04/20 19:43	Reinspection Photo		Load JPG	☒
177	17/04/20 19:43	Reinspection Photo		Load JPG	☒
178	17/04/20 19:43	Reinspection Photo		Load JPG	☒
179	17/04/20 19:43	Reinspection Photo		Load JPG	☒
180	17/04/20 19:43	Reinspection Photo		Load JPG	☒
181	17/04/20 19:43	Reinspection Photo		Load JPG	☒
182	17/04/20 19:43	Reinspection Photo		Load JPG	☒
183	17/04/20 19:43	Reinspection Photo		Load JPG	☒
184	17/04/20 19:43	Reinspection Photo		Load JPG	☒
185	17/04/20 19:43	Reinspection Photo		Load JPG	☒
186	17/04/20 19:43	Reinspection Photo		Load JPG	☒
187	17/04/20 19:43	Reinspection Photo		Load JPG	☒
188	17/04/20 19:43	Reinspection Photo		Load JPG	☒
189	17/04/20 19:43	Reinspection Photo		Load JPG	☒
190	17/04/20 19:43	Reinspection Photo		Load JPG	☒
191	17/04/20 19:43	Reinspection Photo		Load JPG	☒
192	17/04/20 19:43	Reinspection Photo		Load JPG	☒
193	17/04/20 19:43	Reinspection Photo		Load JPG	☒
194	17/04/20 19:43	Reinspection Photo		Load JPG	☒
195	17/04/20 19:43	Reinspection Photo		Load JPG	☒
196	17/04/20 19:43	Reinspection Photo		Load JPG	☒
197	17/04/20 19:43	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
198	17/04/20 19:43	Reinspection Photo		Load JPG	☒
199	17/04/20 19:43	Reinspection Photo		Load JPG	☒
200	17/04/20 19:43	Reinspection Photo		Load JPG	☒
201	17/04/20 19:43	Reinspection Photo		Load JPG	☒
202	17/04/20 19:43	Reinspection Photo		Load JPG	☒
203	17/04/20 19:43	Reinspection Photo		Load JPG	☒
204	17/04/20 19:43	Reinspection Photo		Load JPG	☒
205	17/04/20 19:43	Reinspection Photo		Load JPG	☒
206	17/04/20 19:43	Reinspection Photo		Load JPG	☒
207	17/04/20 19:43	Reinspection Photo		Load JPG	☒
208	17/04/20 19:43	Reinspection Photo		Load JPG	☒
209	17/04/20 19:43	Reinspection Photo		Load JPG	☒
210	17/04/20 19:43	Reinspection Photo		Load JPG	☒
211	17/04/20 19:43	Reinspection Photo		Load JPG	☒
212	17/04/20 19:43	Reinspection Photo		Load JPG	☒
213	17/04/20 19:43	Reinspection Photo		Load JPG	☒
214	17/04/20 19:43	Reinspection Photo		Load JPG	☒
215	17/04/20 19:43	Reinspection Photo		Load JPG	☒
216	17/04/20 19:43	Reinspection Photo		Load JPG	☒
217	17/04/20 19:43	Reinspection Photo		Load JPG	☒
218	17/04/20 19:43	Reinspection Photo		Load JPG	☒
219	17/04/20 19:43	Reinspection Photo		Load JPG	☒
220	17/04/20 19:43	Reinspection Photo		Load JPG	☒
221	17/04/20 19:43	Reinspection Photo		Load JPG	☒
222	17/04/20 19:43	Reinspection Photo		Load JPG	☒
223	17/04/20 19:43	Reinspection Photo		Load JPG	☒
224	17/04/20 19:43	Reinspection Photo		Load JPG	☒
225	17/04/20 19:43	Reinspection Photo		Load JPG	☒
226	17/04/20 19:43	Reinspection Photo		Load JPG	☒
227	17/04/20 19:43	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/04/20 13:00	MARK ESTIMATE		Load PDF	
2	23/04/20 13:26	SUPPLEMENTARY		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20004716/AVF3S2**Date:** 23/04/2020**REFERENCE**

Insured/Claimant:	SM AUTOMOTIVE	Policy No:	DMPCSNA00014622001	
Date of Loss:	27/03/2020	Nature of Claim:	OD	Claim No: SNM20D201523

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN4210S		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4865793
Reg. Date:	16/02/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106140142
Colour:	Silver	Odometer:	253655 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$42,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,320.14	10,854.74	10,465.40	49.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	2,870.00	1,630.00	36.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,820.14	13,724.74	12,095.40	46.84
Approved Total (Overridden) (\$\$)		10,800.00		
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (\$\$)	24,820.14	9,800.00	15,020.14	60.52

INSPECTION

Date of Assignment:	01/04/2020	
Date Inspected:	31/03/2020	Inspected At: SM Automotive BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN4210S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN (WCP)	Cracked	571.50 F	*571.50 F
2	1		*FRONT WINDSCREEN MOULDING (WCP)	Necessary	88.90 F	*88.90 F
3	1		*FRONT WINDSCREEN SEAL (WCP)	Necessary	35.00 F	*35.00 F
4	1		*FRONT BONNET (WCP)	Distorted	571.50 F	*571.50 F
5	2		*FRONT BONNET HINGE (WCP)	Bent	70.00 F	*70.00 F
6	1		*FRONT BONNET INSULATOR (WCP)	Crumpled	190.50 F	*190.50 F
7	8		*FRONT BONNET INSULATOR CLIPS (WCP)	Necessary	12.00 F	*12.00 F
8	1		*FRONT BONNET INNER RUBBER (WCP)	Cut	35.00 F	*35.00 F
9	1		*FRONT BONNET LOCK (WCP)	Jammed	58.00 F	*58.00 F
10	1		*FRONT BONNET LOCK PANEL (WCP)	Bent	58.00 F	*58.00 F
11	2		*FRONT HEAD LAMP (WCP)	O/s Smashed / N/s Cracked	350.00 F	*350.00 F
12	2		*FRONT HEAD LAMP LOWER BRACKET (WCP)	Not Necessary	70.00 F	*- F
13	1		*FRONT BUMPER (WCP)	Distorted	250.00 F	*250.00 F
14	2		*FRONT BUMPER SIDE RETAINER (WCP)	Distorted	70.00 F	*70.00 F
15	10		*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
16	1		*FRONT BUMPER NUMBER PLATE (WCP)	Bent	50.00 F	*50.00 F
17	2		*FRONT BUMPER FOG LAMP (WCP)	Not Necessary	150.00 F	*- F
18	2		*FRONT BUMPER FOG LAMP COVER (WCP)	Not Necessary	130.00 F	*- F
19	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	85.00 F	*85.00 F
20	1		*FRONT BUMPER UNDER COVER (WCP)	Torn	105.00 F	*105.00 F
21	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	175.00 F	*175.00 F
22	1		*FRONT BUMPER CENTRE TOP RUBBER (WCP)	Cut	35.00 F	*35.00 F
23	6		*FRONT BUMPER CENTRE TOP RUBBER CLIPS (WCP)	Necessary	12.00 F	*12.00 F
24	1		*FRONT GRILLE (WCP)	Cracked	135.00 F	*135.00 F
25	1		*FRONT GRILLE INNER (WCP)	Not Necessary	175.00 F	*- F
26	1		*FRONT GRILLE EMBLEM LOGO (WCP)	Necessary	35.00 F	*35.00 F
27	6		*FRONT GRILLE CLIP (WCP)	Necessary	12.00 F	*12.00 F
28	1		*FRONT FENDER (WCP)	O/s Distorted	350.00 F	*175.00 F
29	1		*FRONT FENDER COWLING (WCP)	O/s Deformed	180.00 F	*90.00 F
30	16		*FRONT FENDER COWLING CLIPS (WCP)	Necessary	32.00 F	*16.00 F
31	2		*FRONT FENDER INNER COVER (WCP)	Not Necessary	210.00 F	*- F
32	1		*FRONT SUPPORT PANEL (WCP)	Distorted	330.00 F	*330.00 F
33	2		*FRONT SUPPORT PANEL AIR DUCT (WCP)	Not Necessary	190.00 F	*- F
34	1		*FRONT BATTERY (WCP)	Not Necessary	150.00 F	*- F
35	1		*FRONT BATTERY BRACKET (WCP)	Bent	58.00 F	*58.00 F
36	1		*FRONT BATTERY TRAY (WCP)	Not Necessary	58.00 F	*- F
37	2		*FRONT CHASSIS BRACKET (WCP)	Not Necessary	150.00 F	*- F
38	1		*FRONT AIR-CON CONDENSER (WCP)	Distorted	205.00 F	*205.00 F
39	1		*FRONT AIR-CON SECTION PIPE (WCP)	Bent	250.00 F	*250.00 F
40	1		*FRONT AIR-CON DISCHARGE PIPE (WCP)	Bent	250.00 F	*250.00 F
41	1		*FRONT AIR-CON FAN MOTOR ASSY (WCP)	Not Necessary	380.00 F	*- F
42	1		*FRONT WIPER TANK (WCP)	Deformed	105.00 F	*105.00 F
43	1		*FRONT WIPER TANK MOTOR (WCP)	Not Necessary	105.00 F	*- F
44	1		*FRONT RADIATOR (WCP)	Distorted	450.00 F	*450.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT RADIATOR FAN MOTOR ASSY (WCP)	Distorted	380.00 F	*380.00 F
46	1		*FRONT RADIATOR TANK (WCP)	Deformed	105.00 F	*105.00 F
47	1		*FRONT RADIATOR TOP HOSE (WCP)	Twisted	35.00 F	*35.00 F
48	1		*FRONT RADIATOR INNER HOSE (WCP)	Necessary	35.00 F	*35.00 F
49	2		*FRONT RADIATOR BRACKET (WCP)	Bent	70.00 F	*70.00 F
50	2		*FRONT RADIATOR TOP BRACKET & RUBBER ASSY (WCP)	Necessary	70.00 F	*70.00 F
51	1		*FRONT EXHAUST MANIFOLD (BLACK COLOR) (WCP)	Cut	330.00 F	*330.00 F
52	1		*GUM	Necessary	60.00 FS	*60.00 FS
53	2		*FRONT HORN (WCP)	Broken 1pc Only	90.00 F	*45.00 F
54	1		*FRONT AIR INTAKE RESONATOR (WCP)	Not Necessary	105.00 F	*- F
55	1		*FRONT GEAR BOX MOUNTING (WCP)	Bent	105.00 F	*105.00 F
56	3		*FRONT ENGINE MOUNTING (WCP)	Bent	450.00 F	*450.00 F
57	1		*FRONT ENGINE MOUNTING BRACKET (WCP)	Bent	95.00 F	*95.00 F
58	1		*FRONT ENGINE STARTER (WCP)	Not Necessary	680.00 F	*- F
59	1		*FRONT CENTER CROSS MEMBER (WCP)	Not Necessary	1,200.00 F	*- F
60	1		*FRONT ABS PUMP (WCP)	Broken	2,920.00 F	*1,400.00 F
61	1		*FRONT ABS PIPE ASSY (WCP)	Bent	790.00 F	*580.00 F
62	1		*FRONT AIR-CON VALVE (WCP)	Missing	65.00 F	*65.00 F
63	1		*FRONT AIR-CON TOP-UP PIPE (WCP)	Bent	120.00 F	*120.00 F
64	1		*FRONT COMPRESSOR (WCP)	Not Necessary	450.00 F	*- F
65	1		*FRONT ALTERNATOR (WCP)	Damaged	700.00 F	*550.00 F
66	1		*FRONT WHEEL HOUSING (WCP)	Repair	1,080.00 F	*- F
67	1		*FRONT WIPER GARNISH (WCP)	Not Necessary	145.00 F	*- F
68	1		*FRONT L/H CHASSIS (WCP)	Repair	1,100.00 F	*- F
69	1		*REAR ENGINE MOUNTING BRACKET (WCP)	Bent	125.00 F	*125.00 F
70	1		*FRONT WIRE HARNESS (WCP) (LOCAL REPAIR)	Torn	1,080.00 F	*300.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	19,387.40	9,873.40
+ Margin on L,N Items 10.00/10.00% (S\$)	1,932.74	981.34
Total Parts (S\$)	21,320.14	10,854.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP-UP GAS.	New	280.00	120.00
2	TO REMOVE & REFIT FRONT WINDSCREEN.	New	120.00	120.00
3	TO CHECK WIRING.	New	100.00	30.00
4	PANEL BEATING.	New	2,400.00	1,400.00
5	SPRAY PAINTING.	New	1,600.00	1,200.00
Gross Labour Cost (\$\$)			4,500.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >