

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20004717/T1DS3Q2

**Date:** 13/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700058607

**Claimant**  
**Vehicle No :** SJU4603E **Insured Vehicle No :** SBE9988R

Date of Loss: 27/03/2020 Nature of Claim: TP Claim No: 7548327078SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU4603E		
Make & Model:	VOLKSWAGEN NEW BETTLE, 1.6 (A)	Engine No:	LTA1401442
Reg. Date:	10/12/2009 (Man. Year: 2009)	Chassis No:	WVWZZZ9CZ9M559451
Colour:	Green	Odometer:	131637 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,532.61	1,638.06	1,894.55	53.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	2,400.00	4,120.00	63.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,052.61</b>	<b>4,038.06</b>	<b>6,014.55</b>	<b>59.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	703.68	282.66	421.02	59.83
<b>Nett Amount (S\$)</b>	<b>10,756.29</b>	<b>4,320.72</b>	<b>6,435.57</b>	<b>59.83</b>
<b>+ Loss of Use (3.0 x S\$70.00/day) (S\$)</b>		210.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,532.72</b>		

### INSPECTION

Date of Assignment: 03/04/2020

Date Inspected: 03/04/2020 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,386.50 FS	*1,386.50 FS
2	1		*BUMPER (BUMPER REINFORCEMENT)	Not Necessary	454.64 FS	*- FS
3	1		*AIR DUCT SATIN BLACK (BUMPER LOWER GRILLE)	Not Necessary	103.66 FS	*- FS
4	1		*SUPPORT (BUMPER BRACKET LH )	Not Necessary	346.98 FS	*- FS
5	1		*SUPPORT (BUMPER BRACKET RH)	Not Necessary	346.98 FS	*- FS
6	2		*LICENSE PLATE LIGHT	Not Necessary	64.10 FS	*- FS
7	1		*BACK -UP LIGHT (LH)	Cracked	171.56 FS	*171.56 FS
8	1		*BACK -UP LIGHT (RH)	Not Necessary	178.19 FS	*- FS
9	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
10	1		*REVERSE SENSORS	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **3,532.61** **1,638.06**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	3,360.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,520.00</b>	<b>2,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >