



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 3337P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	2,002.00	-
1	LH FRONT DOOR MIRROR (CHASSIS)	JAMMED	1,170.00	901.23
1	LH FRONT DOOR MIRROR COVER	CUT	407.00	317.22
1	LH FRONT DOOR MIRROR SIGNAL LAMP	NOT DAMAGED	495.00	-
1	FLH FRONT DOOR MIRROR GLASS	NOT DAMAGED	295.00	-
	LESS 10% DISCOUNT		-436.90	-121.85
			3,932.10	1,096.60
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL WIRING.		50.00	50.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	SPRAY PAINTING ON AFFECTED AREAS.		500.00	300.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF LH FRONT DOOR.		500.00	300.00
			1,170.00	650.00
	GRAND TOTAL		5,102.10	1,746.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/GAI20004719/Bqd3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.