



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 8113C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT GRILLE	CRACKED	434.80	434.80
1	FRONT GRILLE EMBLEM	DENTED	1,654.60	1,654.60
1	FRONT O/S HEADLAMP ASSY	MTG CRACKED	1,804.30	1,804.30
1	FRONT BUMPER	CRACKED	1,236.70	1,236.70
1	FRONT BUMPER UPPER REINFORCEMENT	TO REPAIR SEE LABOUR	461.60	-
1	FRONT BUMPER UPPER REINFORCEMENT SPONGE	CRACKED	95.20	95.20
2	FRONT BUMPER UPPER REINFORCEMENT BRACKET @ \$354.10	TO REPAIR SEE LABOUR	708.20	-
1	FRONT BUMPER LOWER REINFORCEMENT	TO REPAIR SEE LABOUR	273.10	-
1	FRONT BUMPER LOWER REINFORCEMENT SPONGE	SERVICEABLE	75.80	-
1	FRONT BUMPER LOWER BUMPER	DENTED / CUT	499.30	499.30
1	FRONT BUMPER LOWER GRILLE	CRACKED	154.70	154.70
1	FRONT NO PLATE HOLDER	SERVICEABLE	122.80	-
1	FRONT O/S BUMPER SIDE RETAINER	SERVICEABLE	155.20	-
	LESS 25% DISCOUNT		-1,919.08	-1,469.90
			5,757.22	4,409.70
<u>SPECIAL NETT ITEMS</u>				
20	FRONT CLIP @ \$2.00 (SN)	NECESSARY	40.00	40.00
1	FRONT NO PLATE (SN)	SERVICEABLE	35.00	-
			75.00	40.00
<u>LABOUR</u>				
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER UPPER REINFORCEMENT, FRONT BUMPER UPPER REINFORCEMENT BRACKET AND FRONT BUMPER LOWER REINFORCEMENT.		500.00	300.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		500.00	220.00
	CHECK AND RECONNECT WIRING.		30.00	15.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DIAGNOSTIC CHECK ON FRONT COLLISION SENSOR AND RESET TO FACTORY SPECIFICATION.	NOT NECESSARY	200.00	-
			1,230.00	535.00
GRAND TOTAL			7,062.22	4,984.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,650.00

Report Ref No. CC4/FCI20004720/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.