

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19022859/GQD3E2-1  
**Date:** 21/04/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80457759QMY
<b>Claimant Vehicle No :</b> SLV8682X	<b>Insured Vehicle No :</b>	SLE3129A
Date of Loss: 26/12/2019	Nature of Claim: TP	Claim No: 616089

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV8682X	Engine No:	HR12275203B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0980141
Reg. Date:	19/01/2018 (Man. Year: 2017)	Odometer:	63431 km
Colour:	Blue		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,820.80	1,666.76	4,154.04	71.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,140.00	2,130.00	65.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,090.80</b>	<b>2,806.76</b>	<b>6,284.04</b>	<b>69.13</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,090.80</b>	<b>2,200.00</b>	<b>6,890.80</b>	<b>75.80</b>

### INSPECTION

Date of Assignment:	31/12/2019	
Date Inspected:	30/12/2019 Inspected At:	Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291 Singapore 569535
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2020)
<b>Parts:</b>	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV8682X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Deformed / Cut	720.00 F	*460.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	52.20 F	*52.20 FL
3	10		*REAR BUMPER CLIPS	Necessary	55.00 F	*30.00 FL
4	1		*REAR BUMPER IMPACT BLOCK LH	Serviceable	115.00 F	*- FL
5	1		*REAR BUMPER IMPACT BLOCK RH	Serviceable	115.00 F	*- FL
6	1		*REAR BUMPER SPONGE	Deformed / Cut	75.00 F	*75.00 FL
7	1		*TAIL GATE ASSY	Dented / Bent	1,150.00 F	*1,018.20 FL
8	1		*TAIL GATE INNER LOCK ASSY	Serviceable	240.00 F	*- FL
9	1		*TAIL GATE LOCK LOWER CATCH	Serviceable	24.00 F	*- FL
10	1		*TAIL GATE WEATHERSTRIP	Serviceable	245.00 F	*- FL
11	1		*TAIL GATE INNER TRIM BOARD	Serviceable	330.00 F	*- FL
12	20		*TAIL GATE INNER TRIM BOARD CLIPS	Serviceable	39.60 F	*- FL
13	1		*TAIL GATE NOTE EMBLEM	Necessary	32.00 F	*32.00 FL
14	1		*TAIL GATE NISSAN LOGO	Necessary	32.00 F	*32.00 FL
15	4		*TAIL GATE OUTER GARNISH CLIPS	Serviceable	8.00 F	*- FL
16	1		*TAIL GATE GAS SHOCK STAY LH	Serviceable	260.00 F	*- FL
17	1		*REAR END PANEL	Serviceable	570.00 F	*- FL
18	1		*REAR END PANEL GARNISH	Distorted / Cut	75.00 F	*75.00 FL
19	1		*SET REAR END PANEL GARNISH CLIPS	Necessary	22.00 F	*22.00 FL
20	3		*REAR END PANEL LOWER STAY BRACKET	Serviceable	68.00 F	*- FL
21	1		*REAR FENDER SPLASH SHIELD LH	Serviceable	85.00 F	*- FL
22	3		*REAR FENDER SPLASH SHIELD CLIPS LH	Serviceable	22.50 F	*- FL
23	1		*REAR FENDER SPLASH SHIELD RH	Serviceable	85.00 F	*- FL
24	3		*REAR FENDER SPLASH SHIELD CLIPS RH	Serviceable	22.50 F	*- FL
25	1		*REAR FENDER AIR VENT LH	Serviceable	55.00 F	*- FL
26	1		*SPARE TYRE BOARD TOP BOARD	Serviceable	175.00 F	*- FL
27	1		*SPARE TYRE SPONGE TRAY	Serviceable	240.00 F	*- FL
28	1		*TAIL LAMP LH	Serviceable	250.00 F	*- FL
29	1		*TAIL LAMP SIDE CLIPS LH	Serviceable	3.00 F	*- FL
30	1		*REVERSE SENSOR	Serviceable	380.00 FS	*- FS
31	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
32	1		*REAR BOOT COMPARTMENT WATER PROOF	Serviceable	120.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
34	1		*REAR NUMBER PLATE HOLDER	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** **5,820.80** **1,846.40**  
**- List Item Discount on L Items 0.00/10.00% (\$\$)** **0.00** **179.64**

**Total Parts (\$\$)** **5,820.80** **1,666.76**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	ANTI RUST TREATMENT	New	150.00	0.00
2	TO CHECK WIRING SYSTEM AND LIGHTS	New	100.00	0.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS TO ASSIST IN REPAIR	New	150.00	100.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	120.00	40.00
5	TO PUTTY AND RESPRAY PAINT ON AFFECTED AREA	New	1,250.00	400.00
6	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR REAR FLOOR PANEL AND ALIGNED ALL PARTS	New	1,500.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>3,270.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >