

22/03/2003

ASS. REC. B.C.

REF: 033/MSA/1022859/Gqd3 Special Instruction:

Surveyor: (110) (Cicero)

Ashik

ASSIGNMENT (Office)

26/3/2020

From (Person):

~~Cyber Lee~~

of

MS14

Date/Time:

~~30/12/19 @ 10:21am~~

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 8682X

Insured:

SLE 3129A

at Workshop m/s

Bak Hong Motor

Tel:

9788 8579

of

BLK 5032 #01-291 AMK Ind. park 2

Policy No:

80457759amy

Claim No:

616089

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/12/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:11am @ 30/12/19

Person Contacted:

kelvin

Vehicle IN / OUT

Date/Time

Action/Instruction

Tel: 9788 8579 (X)

SLV 8682X - X

SLE 3129A - X

31/12/19

Dismantle recovery: 30/12/19
Submit PRS.

\$ 2200, 4 Days.

(Red \$4100, 65%)

Annex A : Assesement / Adjustment on Spare Parts

SLV 8682 X

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
Nett Items						
1	Rear bumper fascia	Defomed/cut	460 1	\$720.00	10%	\$648.00
2	Rear bumper side retainer	Necessary	2	\$52.20	10%	\$46.98
3	Rear bumper clips	Necessary	30 10	\$55.00	10%	\$49.50
4	Rear bumper impact block LH	Slack/distorted	1	\$115.00	10%	\$103.50
5	Rear bumper impact block RH	Slack/distorted	1	\$115.00	10%	\$103.50
6	Rear bumper sponge	Defomed/cut	1	\$75.00	10%	\$67.50
7	Tail gate assy	Dented/bent	10/8.2 1	\$1,150.00	10%	\$1,035.00
8	Tail gate inner lock assy	Bent/jammed	1	\$240.00	10%	\$216.00
9	Tail gate lock lower catch	Bent	1	\$24.00	10%	\$21.60
10	Tail gate weatherstrip	Deformed	1	\$245.00	10%	\$220.50
11	Tail gate inner trim board	Grazed/cut	1	\$330.00	10%	\$297.00
12	Tail gate inner trim board clips	Necessary	20	\$39.60	10%	\$35.64
13	Tail gate "NOTE" emblem	Necessary	1	\$32.00	10%	\$28.80
14	Tail gate "NISSAN" logo	Necessary	1	\$32.00	10%	\$28.80
15	Tail gate outer garnish clips	Necessary	4	\$8.00	10%	\$7.20
16	Tail gate gas shock stay LH	Distorted/dragging	1	\$260.00	10%	\$234.00
17	Rear end panel	Repair	1	\$570.00	100%	\$0.00
18	Rear end panel garnish	Distorted/cut	1	\$75.00	10%	\$67.50
19	Rear end panel garnish clips	Necessary	1set	\$22.00	10%	\$19.80
20	Rear end panel lower stay bracket	Bent	3	\$68.00	10%	\$61.20
21	Rear fender splash shield LH	Grazed/cut	1	\$85.00	10%	\$76.50
22	Rear fender splash shield clips LH	Necessary	3	\$22.50	10%	\$20.25
23	Rear fender splash shield RH	Grazed/cut	1	\$85.00	10%	\$76.50
24	Rear fender splash shield clips RH	Necessary	3	\$22.50	10%	\$20.25
25	Rear fender air vent LH	Shifted/cut	1	\$55.00	10%	\$49.50
26	Spare tyre board top board	Cut	1	\$175.00	10%	\$157.50
27	Spare tyre sponge tray	Deformed	1	\$240.00	10%	\$216.00
28	Tail lamp LH	Grazed	1	\$250.00	10%	\$225.00
29	Tail lamp side clips LH	Necessary	1	\$3.00	10%	\$2.70
S/Nett Items						
30	Reverse sensor	Distorted/faulty	1set	\$380.00	X	\$380.00
31	Rear windscreen glass sealant	Necessary	150 1	\$80.00	X	\$80.00
32	Rear boot compartment water proof	Necessary	1	\$120.00	X	\$120.00
33	Rear number plate	Grazed/dented	1	\$35.00	X	\$35.00
34	Rear number plate holder	Grazed/bent	1	\$40.00	X	\$40.00
Total for Spare Parts :				\$5,820.80		\$4,791.22

(786.4

10% : 1616.76

Annex B : Adjustment on Labour and Spray Painting

SLV 8682 X

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	Anti rust treatment	\$150.00	\$120.00 X
2	To check wiring system and lights	\$100.00	\$80.00 X
3	To remove & refix rear windscreen glass to assist in repair	\$150.00	\$120.00 100
4	To remove & replace reverse sensor	\$120.00	\$80.00 40
5	To putty and respray paint on affected area	\$1,250.00	\$1,000.00 400
6	To renew damaged parts, straighten/repair rear floor panel and aligned all parts.	\$1,500.00	\$1,200.00 600
TOTAL FOR LABOUR & SPRAY PAINTING :		<u>\$3,270.00</u>	<u>\$2,600.00</u>

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$5,820.80	\$4,791.22
TOTAL FOR LABOUR & SPRAY PAINTING :	\$3,270.00	\$2,600.00
TOTAL REPAIR COSTS :	<u>\$9,090.80</u>	<u>\$7,391.22</u>

2256.76

20/2: 2200

4 Days