



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG19011969/Ntf3s2-1

c/o: KELVIN C.H.I.A PARTNERSHIP
6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC
TOWER FOUR SINGAPORE 038986

Date : 24-04-2020



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFK 58E	Veh. Inspected	FBH 7373L
Policy No.	2100382060	Coverage (\$)	0.00
Claim No.	8074876779SG	Excess (\$)	0.00
Assign From	TEO YI XUAN	Assign Date	31/03/2020

2. Vehicle Particulars & Condition

Make & Model	HARLEY DAVIDSON	c.c	1802
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	5HD1TC8C7DB958615	Colour	GOLD
Odometer	31960	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	130/60 R23	METZELER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	200/55 R17	METZELER	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/06/2019	Inspection Date	08/07/2019
Survey held at	Vicious Cycles Parts & Service 71 Woodlands Ave 10, #01-13 Woodlands Ind. Xchange Singapore 737743		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**